

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0978/2021/JT
DATE : 2-Dec-21
WIP : 56503

Xiao Chen.
\$27298.28.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: (880 4602 - Fax: 6880 4838

OWNER'S NAME	:	MR EZEKIEL PAUL JAMES EMMANUEL
ADDRESS	:	50 TANAH MERAH KECHIL #03-04 SINGAPORE 465524
TELEPHONE	:	HP +65 91298563
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070162597
VEHICLE NO	:	SFY 806 P
MODEL CODE	:	AUDI A4 2.0 TFSI S TRONIC
MODEL YEAR	:	17/11/2020
ENGINE NO	:	DEM 026746
CHASSIS NO	:	WAUZZZF42MA011901
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	1-Dec-21
PLACE OF ACCIDENT	:	JUNCTION OF NEIL ROAD AND CANTONMENT ROAD

PREMIUM AUTOMOBILES

SS 081 QAD 1 SINGAPORE 402699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFY 806 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	X
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 700.00	560 ✓
3	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00	✓ ✓
4	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OR RHS REAR FENDER.	S/N \$ 600.00	✓
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN, 1/4 GLASS AND RHS FRONT DOOR WINDOW GLASS.	S/N \$ 400.00	✓ ✓
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	150 ✓
SUB TOTAL LABOUR CHARGES		: \$ 2,740.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFY 806 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGED AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	✓
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN ATRRAC, ETC	S/N \$ 1,400.00	✓
9	TO DISMANTLE AND REINSTALL FRONT BUMPER AND REAR BUMPER. TO CUT OUT AND WELD RHS REAR FENDER. TO RENEW RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,700.00	4000 ✓
10	TO RESPRAY REAR BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, RHS WING MIRROR COVER, DOOR HANDLES, RHS REAR DOOR, RHS REAR FENDER, RHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCE, ROOF CHANNEL AND REAR END PANELLING.	\$ 7,700.00	Handle x 2 = 1000 = 2000 Mirror : 150
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		\$ 21,132.00	3925 ✓

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFY 806 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER - RH <i>Reps</i>	1	\$ 1,092.00	X
2	FRONT FENDER ATTACHEMENT PARTS	1	\$ 202.00	✓
3	FRONT FENDER BRACE - RH	1	\$ 118.00	✓
4	FRONT FENDER BRACE COVER - RH	1	\$ 31.00	✓
5	HEADLAMPS COVER - RH	1	\$ 44.00	X
6	FRONT DOOR - RH <i>Dented</i>	1	\$ 3,192.00	✓ 2553.60
7	FRONT DOOR OUTER SEAL - RH <i>Nec</i>	1	\$ 205.00	✓ 164.00
8	BONDING AGENT	1	\$ 49.00	X
9	CLEANING SOLUTION	1	\$ 68.00	X
10	APPLICATOR	1	\$ 8.00	X
11	FRONT DOOR ATTACHEMENT PARTS <i>Nec</i>	1	\$ 1,050.00	✓
12	FRONT DOOR CATCH - RH <i>Nec</i>	1	\$ 105.00	X
13	FRONT DOOR CATCH TRIM PLATE - RH <i>Reps</i>	1	\$ 88.00	✓
14	FRONT DOOR MOUNTING BAR - RH	1	\$ 164.00	✓
15	FRONT WINDOW REGULATOR - RH <i>new</i>	1	\$ 282.00	✓
16	FRONT WING MIRROR MOUNTING - RH <i>ut</i>	1	\$ 1,089.00	✓ 871.20
17	FRONT WING MIRROR CAP - RH <i>missing</i>	1	\$ 289.00	✓ 231.20
18	FRONT WING MIRROR GLASS - RH <i>ut</i>	1	\$ 1,667.00	✓ 1333.60
19	FRONT WINDOW SLOT SEAL TRIM STRIP - RH <i>new</i>	1	\$ 307.00	✓
20	FRONT WINDOW GUIDE TRIM STRIP <i>ut</i>	1	\$ 257.00	✓ 205.20
SUB TOTAL SPARE PARTS		:	\$ 10,307.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183


EMAIL: NOPA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFY 806 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT DOOR WINDOW - RH <i>new</i>	1	\$ 290.00	+
22	FRONT TYRE PRESSURE DATA PLATE <i>new</i>	1	\$ 38.00	✓ 31.28
23	REAR DOOR - RH <i>Dented</i>	1	\$ 3,192.00	✓ 2553.60
24	REAR DOOR OUTER SEAL - RH <i>new</i>	1	\$ 205.00	✓ 164
25	BONDING AGENT <i>new</i>	1	\$ 49.00	X
26	CLEANING SOLUTION <i>new</i>	1	\$ 68.00	X
27	APPLICATOR <i>new</i>	1	\$ 8.00	X
28	REAR DOOR SEALING STRIP <i>new</i>	1	\$ 17.00	+
29	REAR DOOR ATTACHEMENT PARTS <i>new</i>	1	\$ 860.00	+
30	REAR DOOR CATCH - RH <i>new</i>	1	\$ 120.00	X
31	REAR DOOR MOUNTING BAR - RH <i>new</i>	1	\$ 164.00	X
32	REAR DOOR HANDLE TRIM PLATE - RH <i>missing</i>	1	\$ 88.00	✓ 69.92
33	REAR DOOR HOUSING - RH <i>new</i>	1	\$ 8.00	✓ 5.92
34	REAR DOOR COVER - RH <i>new</i>	1	\$ 6.00	✓ 4.64
35	REAR DOOR HANDLE SENSOR - RH <i>? Damaged</i>	1	\$ 228.00	✓ 182.40 ✓
36	REAR DOOR HANDLE - RH <i>new</i>	1	\$ 44.00	X
37	REAR PERIPHERAL LIGHT - RH <i>new</i>	1	\$ 72.00	X
38	FRONT UNDERLAY - RH <i>new</i>	1	\$ 4.00	X
39	REAR UNDERLAY - RH <i>new</i>	1	\$ 4.00	X
40	REAR FENDER - RH <i>Dented</i>	1	\$ 4,052.00	✓ 3241.60
SUB TOTAL SPARE PARTS		:	\$ 9,517.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHALID@PREMIUMAUTO.COM S@V@CATMS@PREMIUMAUTO.COM

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFY 806 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	REAR WINDOW { nec	1	\$	1,154.00	✓ 923.20
42	REAR SIDE WINDOW - RH	1	\$	656.00	✓ 524.40
43	PRIMER { nec	2	\$	40.00	✓ 31.52
44	INSERT	1	\$	89.00	✓ 71.04
45	REAR WHEEL HOUSING LINER - RH	1	\$	240.00	✗
46	ACYLIC SEALANT { nec	S/N	\$	180.00	✓
47	CAVITY WAX	S/N	\$	140.00	✓
48	STONE CHIP	S/N	\$	180.00	✓
49	METAL FILLER POWDER { nec	S/N	\$	280.00	✓
50	1/4 GLASS SEALANT	S/N	\$	100.00	✓
51	REAR WINDSCREEN SEALANT	S/N	\$	200.00	✓
52	SUNDRIES { nec		\$	500.00	✓ 32.72
TOTAL SPARE PARTS		:	\$	23,583.00	
TOTAL LABOUR CHARGES		:	\$	21,132.00	
GRAND TOTAL		:	\$	44,715.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 LIBI ROAD 1, SINGAPORE 408699

TEL: 6766 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adnan
02/12/21

Not Authorised, 15 days
H.S.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT