

Our Job Ref No : 305496408
Date : 06/12/21

ENGINEERING
ComfortCarCare Engineering Pte Ltd
59 Loyang Drive, Singapore 508999
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : THEVAN
Vehicle Reg No. : SHD3985Y

Fax : _____
01/12/21

The survey and estimates of the repairs of the above mentioned vehicle are as follows:-

- 1. The repair job shall bill to NTUC SMJ7621E
- 2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges _____
 - Total for Part-By-Part Repair Cost** _____
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost \$1,000.00
- 3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.  We confirm the estimates and finalized amount 
Signature: _____ Signature: _____
Name : CHIANG Name : Thevan
Tel : 62148314 Date : 2/12/21
Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks: _____

REPAIR ESTIMATE*

VEHICLE NO SHD3985Y ✓

DATE 01/12/2021 16.10

L/S

MAKE REG.06.08.2021

MODEL : HYUNDAI IONIQ G2

CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			cut ✓ \$430.90
1	FRONT BUMPER BRACKET LH			nil ✓ \$35.00
1	HEADLAMP LH		SVC X	\$1,993.60
1	FRONT BUMPER MOULDING CENTRE UPPER E RH		SVC X	\$368.50
1	DAY LIGHT LH		SVC X	\$642.50
1	FRONT BUMPER GRILLE LH		SVC X	\$186.90
1	FRONT WHEEL HUB COVER LH		SVC 0.7 X	\$346.40
	SUB TOTAL			\$4,003.80
	20.00%			\$800.76
	DISCOUNTED TOTAL			\$3,203.04
	Labour Charge			
	Panel Beating		350	\$520.00
	Spray Paint		500 500	\$600.00
	Reset front wheel alignment		NW X	\$60.00
	Check lighting		20	\$60.00
	TOTAL LABOUR			\$1,240.00
	ESTIMATE TOTAL			\$4,443.04

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thwan@lkhauto.com
 822 35769
 2/12/21 1545
 L/S ✓ after repair photo
 ✗ 2 days w/p ✓

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer