

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21012295/VQF3N2**Date:** 13/12/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ003481
Claimant Vehicle No :	SHC7767P	Insured Vehicle No :	GBD1437Y
Date of Loss:	03/12/2021	Nature of Claim:	TP
		Claim No:	M2105605

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC7767P	Engine No:	G4LEJU192193
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU141416
Reg. Date:	30/04/2019 (Man. Year: 2018)	Odometer:	147359 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,867.56	1,654.84	2,212.72	57.21
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,430.00	1,810.00	620.00	25.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,308.56	3,475.84	2,832.72	44.90
+ GST 7.00/7.00% (S\$)	441.60	243.31	198.29	44.90
Nett Amount (S\$)	6,750.16	3,719.15	3,031.01	44.90

INSPECTION

Date of Assignment:	06/12/2021		
Date Inspected:	06/12/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 13 Dec 2021)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SHC7767P)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT FENDER RH	Repair	588.80 FL	-	*- FL
2	1		*FRT FENDER SHIELD RH	Serviceable	164.70 FL	-	*- FL
3	1		*FRT WHEEL CAP RH	Scratched	346.40 FL	-	*346.40 FL
4	1		*FRT DOOR RH	Repair	1,797.20 FL	-	*- FL
5	1		*FRT DOOR GLASS RH	Repair	215.20 FL	-	*- FL
6	1		*FRT DOOR OUTER MOULDING RH	Necessary	110.10 FL	-	*110.10 FL
7	1		*WING MIRROR RH	Cut	1,391.70 FL	-	*1,391.70 FL
8	1		*FRT DOOR COMFORTDELGRO RH	Necessary	75.00 F	-	*75.00 FS
9	1		*REAR DOOR APPS RH	Necessary	80.00 F	-	*80.00 FS
10	1		*FRT FENDER BLUE-DRIVE RH	Necessary	26.60 FL	-	*26.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,795.70	2,029.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	928.14	374.96
Total Parts (\$\$)	3,867.56	1,654.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	700.00
2	SPRAY PAINTING	New	1,200.00	1,000.00
3	CHECK WIRINGS	New	50.00	20.00
4	TUFF KOTE	New	80.00	30.00
5	TRANSFER OF DOOR	New	120.00	0.00
6	WHEEL ALIGNMENT	New	120.00	0.00
7	TOWING FEE	New	60.00	60.00
			Gross Labour Cost (\$\$)	2,430.00
				1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >