

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd  
20 McCallum Street  
#09-01 Tokio Marine Centre  
Singapore 069046

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Wan Cong

Date: 09 Dec 2021

## **Preliminary Advice**

Insured : GBD1437Y  
Vehicle No  
TP Vehicle No : SHC7767P  
Accident Date : 03/12/2021  
Make : HYUNDAI IONIQ HYBRID  
Assignment Date : 06/12/2021  
Date of Inspection : 06/12/2021  
Est. Duration of Repair : 3  
Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)  
59 LOYANG DRIVE  
SINGAPORE 508969

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,308.56
Revised Amount	:S\$	3,495.84
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,495.84

Lump Sum Repair :S\$

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.