

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

20-10-2021



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 59829
Date Estimated : 19/10/2021
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Electronics & Engineering Co. Ltd
285 Outram Road

Singapore 169069

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBQ18L	WBS8M92050P972542	23/05/2016	M3 SEDAN	62035

DESCRIPTION

VALUE

To replace front bumper, front center air duct including to knock out dented area caused by the accident

850 / 1,700.00

To respray front bumper

986 / 1,038.00

To replace right headlight. 456

3 / 481.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

177.00

To check electrical wiring system at the front section for proper function including adjustment of headlights.

168 / 177.00

To supply front emboss number plate.

83.00

Sundries.

80 / 150.00

Total Labour 1: 3,806.00

DESCRIPTION

QTY

PRIC

VALUE

FRT BUMPER TOP MOUNT	1	380.95	380.95
# FRT SHOCK ABSORBER M ECE	1	62.10	62.10
# INSERT AIR INLET MIDDLE	1	106.10	106.10
# FRT BUMPER BOTTOM CARRIER	1	355.50	355.50
# Cover, registration plate	1	97.85	97.85
# FRT BUMPER PANEL PRIMED (SRA	1	1,354.90	1,354.90
# FRT BUMPER REPAIR KIT HOLDER	1	86.45	86.45
# Grille, front right	1	148.65	148.65
# Grille, front left	1	148.65	148.65
GROMMET	2	0.80	1.60
# AIR DUCT RADIATOR	1	105.90	105.90
# ADAPTER AIR DUCT (M)	1	52.95	52.95
PLAQUE 82MM	1	71.95	71.95
# RH HEADLIGHT LED AHL	1	3,088.85	3,088.85

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : b1 59829
Date Estimated : 19/10/2021
Prepared By : Foong Shiuh Jye

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBQ18L	WBS8M92050P972542	23/05/2016	M3 SEDAN	62035

Total Parts : 6,062.40

Steve (LKK)
7/12/21, 11.30am

W PL
3 yrs
P/P
by Bel sy

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

10,458.10



Labour 1	:	3,806.00
Parts	:	6,062.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	690.79
Grand Total	:	10,559.19

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **