

PROVI AUTOWORKS PTE LTD.

Blk 8 , Kaki Bukit Avenue 4 , #02-24

Premier @ Kaki Bukit Singapore 415875

Email: claims@PROVIAUTO.com

Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -20%	
SN	
Labour	
Total	
Lump Sum	
ERV	51K

uilion

TO: III
Vehicle : SMP 6553 T
Make & Model : TOYOTA AQUA
DATE: 6/12/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	FRONT BUMPER <i>3M</i>	1	\$ 1,501.70	\$ 1,501.70
2	FRONT BUMPER SIDE RETAINER <i>3M</i>	2	\$ 125.00	\$ 250.00
3	FRONT FENDER RH <i>Deated</i>	1	\$ 706.50	\$ 706.50
4	FRONT FENDER QUARTER GARNISH RH <i>new</i>	1	\$ 97.80	\$ 97.80
5	FRONT FENDER EMBLEM (HYBRID) <i>new</i>	1	\$ 120.00	\$ 120.00
6	FRONT FENDER INNER COWLING RH <i>ton</i>	1	\$ 178.90	\$ 178.90
7	FRONT ABSORBER LH <i>3</i>	1	\$ 398.60	\$ 398.60
8	FRONT LOWER ARM LH <i>3M</i>	1	\$ 672.30	\$ 672.30
9	FRONT KNUCKLE ARM LH <i>3M</i>	1	\$ 890.00	\$ 890.00
10	FRONT WHEEL BEARING LH <i>3M</i>	1	\$ 289.00	\$ 289.00
11	FROTN ORIGINAL RIM LH <i>3M</i>	1	\$ 879.00	\$ 879.00
12	FRONT DOOR RH <i>Deated</i>	1	\$ 1,097.50	\$ 1,097.50
13	FRONT DOOR BLACK STICKER GARNISH RH <i>new</i>	2	\$ 45.00	\$ 90.00
14	FRONT DOOR OUTER MOULDING RH <i>lot</i>	1	\$ 198.00	\$ 198.00
15	FRONT DOOR OUTER HANDLE RH <i>Regis</i>	1	\$ 267.00	\$ 267.00
16	FRONT DOOR OUTER HANDLE COVER RH <i>Regis</i>	1	\$ 45.00	\$ 45.00
17	FRONT DOOR INNER TRIM RH <i>new</i>	1	\$ 578.20	\$ 578.20
18	FRONT DOOR INNER LOCK RH <i>new</i>	1	\$ 312.00	\$ 312.00
19	FRONT DOOR LOCK CATCH RH <i>new</i>	1	\$ 56.00	\$ 56.00
20	FRONT DOOR WEATHERSTRIP RH <i>new</i>	1	\$ 198.00	\$ 198.00
21	FRONT DOOR REGULATOR MOTOR RH <i>new</i>	1	\$ 457.30	\$ 457.30
22	FRONT DOOR REGULATOR GEAR RH <i>new</i>	1	\$ 322.00	\$ 322.00
23	FRONT DOOR CHANNEL RH <i>3M</i>	1	\$ 98.00	\$ 98.00
24	FRONT DOOR CHANNEL SEAL RH <i>3M</i>	1	\$ 155.20	\$ 155.20
25	ROCKER PANEL <i>Regis</i>	1	\$ 1,254.00	\$ 1,254.00
26	CENTER PILLER OUTER <i>Regis</i>	1	\$ 1,212.00	\$ 1,212.00
27	REAR DOOR RH <i>Regis</i>	1	\$ 1,045.20	\$ 1,045.20
28	REAR DOOR BLACK STICKER GARNISH RH <i>new</i>	2	\$ 45.00	\$ 90.00
29	REAR DOOR OUTER MOULDING RH <i>lot</i>	1	\$ 198.00	\$ 198.00
30	RAER DOOR INNER TRIM RH	1	\$ 594.00	\$ 594.00
31	REAR DOOR INNER LOCK RH <i>3M</i>	1	\$ 298.50	\$ 298.50
32	REAR DOOR LOCK CATCH RH <i>3M</i>	1	\$ 56.00	\$ 56.00
33	REAR DOOR WEATHERSTRIP RH	1	\$ 198.00	\$ 198.00
34	DRIVER SEAT BELT <i>3M</i>	1	\$ 954.00	\$ 954.00
35	SRS AIRBAG CONTOR UNIT <i>3M</i>	1	\$ 1,258.00	\$ 1,258.00
	Subtotal :		\$	17,015.70
	Less 20%		\$	3,403.14
	Parts Total :		\$	13,612.56

2553-90
1915.42

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	FRONT BUMPER CLIP <i>Mem</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
2	FRONT TYRE RH <i>Mem</i>	1	\$ 450.00	\$ 450.00 <i>+</i>
3	FRONT DOOR INNER TRIM CLIP SET <i>Mem</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
4	REAR DOOR INNER TRIM CLIP SET <i>Mem</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
5	RIM HUP CAP <i>Coated</i>	1	\$ 500.00	\$ 500.00 <i>100</i>
6	CENTER PILLER SEALANT <i>3 x 1/2</i>	1	\$ 120.00	\$ 120.00 <i>+</i>
7	ROCKER PANEL SEALANT <i>3 m</i>	1	\$ 120.00	\$ 120.00 <i>130</i>
				\$ 1,340.00

LABOUR		PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS		\$ 1,800.00 <i>700</i>
TO SPRAY PAINT AFFECTED AREA		\$ 1,800.00 <i>800</i>
TO PERFORM LIGHTING & WIRING CHECK		\$ 150.00 <i>30</i>
TO APPLY ANTI-RUST & TUFF KOTE		\$ 250.00 <i>80</i>
REMOVE AND INSTALL FRONT DOOR PART		\$ 180.00 <i>80</i>
REMOVE AND INSTALL REAR DOOR PART		\$ 180.00 <i>+</i>
REMOVE AND INSTALL CARPET, SEAT AND INTERIOR		\$ 450.00 <i>+</i>
REMOVE AND INSTALL FRONT UNDER CARRIAGE		\$ 600.00 <i>+</i>
TO CHECK FOUR WHEEL ALIGNMENT		\$ 120.00 <i>80</i>
		<i>1770</i>
LABOUR TOTAL		\$ 5,530.00

Total Parts Cost	\$ 14,952.56
Total Labour Cost	\$ 5,530.00
Total Repair Cost	\$ 20,482.56

APPROVED DETAILS
 NO. OF WORKING DAYS
 PART BY PART OR LUMP SUM
 DATE & TIME OF SURVEY
 SURVEYED BY
 CONTACT NUMBER
 FAX NUMBER

total: 381542
2/s: 3050
04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature
 Date