

Justin

SJE :

Vehicle Nos : **SLF 6370 T**

Date of Survey :

Model : **TOYOTA HARRIER**

Date of ReSurvey:

After-Paint:

Year : **20116**

Contacts :

Chassis No : **ZSU600074569**

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

2016

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	TAILGATE	1	\$ 1,821.50	\$ 1369.50 1,821.50
2	TAILGATE LOGO	1	\$ 68.40	\$ ✓ 68.40
3	TAILGATE EMBLEM 'HARRIER'	1	\$ 95.40	\$ 75.30 95.40
4	TAILGATE OUTER GARNISH	1	\$ 490.50	\$ 402.20 490.50
5	TAILGATE LOCK ASSY	1	\$ 497.35	\$ 355.50 497.35
6	TAILGATE STRIKER	1	\$ 41.50	\$ 41.50
7	TAILGATE INNER TRIM BOARD	1	\$ 581.60	\$ ✓ 581.60
8	TAILGATE ELECTRICAL DAMPER	2	\$ 660.50	\$ 1,321.00
9	TAILGATE HINGES	2	\$ 68.50	\$ 137.00
10	TAILGATE WEATHERSTRIP	1	\$ 341.66	\$ ✓ 341.66
11	TAILGATE LAMP LH 1	2 ✓	\$ 559.00 685.20	\$ 559.00 1,370.40
12	TAILGATE WINDSCREEN MOULDING	1	\$ 195.20	\$ 133.00 195.20
13	TAILGATE SMART KEYLESS SENSOR	1	\$ 230.50	\$ 230.50
14	TAILGATE BUZZER	1	\$ 188.30	\$ 188.30
15	REAR BUMPER	1	\$ 1,675.30	\$ 1381.00 1,675.30
16	REAR BUMPER LOWER	1	\$ 501.60	\$ 453.20 501.60
17	REAR BUMPER SIDE RETAINER	2	\$ 75.40 170.00	\$ 150.80 340.00
18	REAR BUMPER BRACKET	2	\$ 68.50	\$ ✓ 137.00
19	REAR BUMPER REINFORCEMENT	1	\$ 715.00	\$ 715.00
20	REAR BUMPER SPONGE	1	\$ 227.80	\$ 127.80 227.80
21	REAR BUMPER REFLECTOR	1	\$ 156.90	\$ 156.90
22	REAR END PANEL	1	\$ 921.30	\$ 715.50 921.30
23	REAR END PANEL TOP GARNISH	1	\$ 397.40	\$ 321.30 397.40
24	SPARE TYRE PANEL	1	\$ 796.38	\$ ✓ 796.38
25	SPARE TYRE PANEL TOP BOARD	1	\$ 733.40	\$ 733.40
26	SPARE TYRE PANEL TOOLS TRAY	1	\$ 507.30	\$ 507.30
27	TAILLAMP	2	\$ 592.70 885.20	\$ 1185.40 1,770.40
28	TAILLAMP LOWER BRACKET	2	\$ 104.50	\$ 209.00
29	REAR FENDER LH	1	\$ 1,476.00	\$ 1,476.00
30	FENDER INNER TRIM BOARD	2	\$ 825.00	\$ 1,650.00

DDV
NEC
BRV
JM
NDX
BRV
NDX
NDX
TNV
BRV
NEC
NNX
NNX
BRV
BRV
NEC
NEC
NSX
BRV
NDX
DDV
BRV
DDV
NDX
BRV
NSX
DDX
NDX

Parts Sub Total : \$ 9154.54 19,595.09

Discount : \$ 2288.64 4,898.77

PARTS TOTAL : \$ 6865.91 14,696.32

6865.91

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	SUNDRIES	1	\$ 80.00	\$ 80.00	NNX
2	TAILGATE SEALANT	1	\$ 100.00	\$ <u>30.00</u> 100.00	NECV
3	TAILGATE OUTER GARNISH CLIPS	1	\$ 50.00	\$ <u>30.00</u> 50.00	NECV
4	TAILGATE INNER TRIM BOARD CLIPS	1	\$ 60.00	\$ <u>30.00</u> 60.00	NECV
5	TAILGATE LAMP SEAL	2	\$ 60.00	\$ <u>60.00</u> 120.00	NECV
6	TAILGATE LAMP CLIPS	2	\$ 50.00	\$ 100.00	NSX
7	TAILGATE WINDSCREEN SEALANT	1	\$ 100.00	\$ <u>60.00</u> 100.00	NECV
8	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	NNX
9	TAILGATE WINDSCREEN PRIMER AND CLEANER	1	\$ 80.00	\$ 80.00	NNX
10	REAR BUMPER CLIPS	1	\$ 50.00	\$ <u>30.00</u> 50.00	NECV
11	REAR BUMPER LOWER CLIPS	1	\$ 50.00	\$ <u>30.00</u> 50.00	NECV
12	REAR BUMPER REVERSE SENSOR	2	\$ 250.00	\$ <u>200.00</u> 500.00	SCV
13	REAR END PANEL SEALANT	1	\$ 100.00	\$ <u>30.00</u> 100.00	NECV
14	REAR END PANEL TOP GARNISH CLIPS	1	\$ 50.00	\$ <u>20.00</u> 50.00	NECV
15	TAILMAP SEAL	2	\$ 60.00	\$ <u>60.00</u> 120.00	NECV
16	TAILLAMP CLIPS	2	\$ 50.00	\$ 100.00	NNX
17	REAR FENDER INNER TRIM BOARD CLIPS	2	\$ 50.00	\$ 100.00	NNX
18	REAR NUMBER PLATE W/CASING	1	\$ 80.00	\$ 80.00	NNX
SPECIAL NETT TOTAL :				\$ 1,900.00	
				580.00	

Nos.	LABOUR	S\$	
1	R&R TAILGATE COMPONENT	\$ <u>80.00</u> 150.00	✓
2	R&R TAILGATE WINDSCREEN	\$ <u>120.00</u> 250.00	✓
3	R&R REAR BUMPER REVERSE SENSOR	\$ <u>60.00</u> 100.00	✓
4	DIAGNOSTIC RESET FAULT CODE	\$ <u>120.00</u> 300.00	✓
5	CHECK WIRING	\$ <u>30.00</u> 100.00	✓
6	UPHOLSTERY	\$ 300.00	NNX
7	PANEL BEATING	\$ <u>1000.00</u> 1,600.00	✓
8	RUST PROOFING	\$ 200.00	NNX
9	SPRAY PAINTING	\$ <u>1000.00</u> 1,600.00	✓
LABOUR TOTAL :		\$ 4,600.00	
		2410.00	

Survey Resurvey Lump sum repair
 6/12/2021 7/12/2021 Repair days 8
 15/15 hrs 1700 hrs
 TGRIM hr TGRIM hr

PARTS TOTAL : \$ 14,696.32
 SPECIAL NETT TOTAL : \$ 1,900.00
 LABOUR TOTAL : \$ 4,600.00
 GRAND TOTAL : \$ 21,196.32

Parts 6865.91
 SN 580.00
 Labour 2410.00
 9855.91
 @ 20% 1971.18
 7884.72

LS 7850/2
 TGRIM hr
 12/2/2022

L&K Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company