

TO :

ESTIMATE REPORT

1ST Quotation

FAX NO:

07/12/2021 11:49

JOB-NO: 50113793

Page 1 of 3

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA8843G

TRANS: AUTO

CHASSIS: JTDKB3FU403538763

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZRR969408

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,800.00	0.00	1,800.00	900	Y	_____
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	180.00	0.00	180.00	30	Y	_____
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	1.00	350.00	0.00	350.00	50	Y	_____
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	300.00	0.00	300.00	30	Y	_____
5 TO REFIT REAR REVERSE SENSOR	1.00	140.00	0.00	140.00	30	Y	_____
6 TO TRANSFER REAR BOOT MECHANISM TO NEW BOOT AND TO PERFORM WATER SEEPAGE TEST	1.00	180.00	0.00	180.00	50	Y	_____
7 TO REMOVE AND REFIT REAR TAILGATE UPPER AND LOWER WINDSCREEN TO ENABLE BODYWORK REPAIR	1.00	270.00	0.00	270.00	150	Y	_____
8 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	150.00	0.00	150.00	X	Y	_____
9 TO CHECK AND REPAIR WIRE HARNESS	1.00	220.00	0.00	220.00	X	Y	_____
10 TO VACUUM SHATTERED REAR WINDSCREEN GLASS AND WASH REAR PASSENGER SEAT	1.00	180.00	0.00	180.00	30	Y	_____
11 TO RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	200	Y	_____
12 TO RESPRAY REAR BUMPER EXTENSION FILLER	1.00	250.00	0.00	250.00	X	Y	_____
13 TO RESPRAY REAR REVERSE SENSOR	1.00	250.00	0.00	250.00	50	Y	_____
14 TO RESPRAY REAR QUARTER PANEL	1.00	250.00	0.00	250.00	200	Y	_____
15 TO RESPRAY TAILLAMP PANEL	1.00	250.00	0.00	250.00	80	Y	_____
16 TO RESPRAY REAR TAILGATE PANEL	1.00	250.00	0.00	250.00	200	Y	_____
17 TO RESPRAY REAR TAILGATE OUTER GARNISH	1.00	250.00	0.00	250.00	150	Y	_____
18 TO RESPRAY REAR TAILGATE SPOILER	1.00	250.00	0.00	250.00	X	Y	_____
19 TO RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00	200	Y	_____
20 TO RESPRAY REAR FLOOR PAN	1.00	250.00	0.00	250.00	X	Y	_____
21 TO RESPRAY REAR FLOOR PAN EXTENSION	1.00	250.00	0.00	250.00	X	Y	_____
22 TO REAPPLY SEAL JOINT ON WELDING AFFECTED AREAS	1.00	180.00	0.00	180.00	X	Y	_____
TOTAL:		6,700.00	0.00	6,700.00			_____

MATERIALS

L-2350

G-STAR-WI-ET-001-02-Rev00

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
1 REAR BUMPER COVER / DD	1.00	442.60	110.65	331.95	L	Y	
2 REAR BUMPER CENTER GUARD / CRU	1.00	576.30	144.08	432.22	L	Y	
3 REAR LH BUMPER RETAINER / BR	1.00	116.50	29.13	87.37	L	Y	
4 REAR RH BUMPER RETAINER / BR	1.00	117.70	29.43	88.27	L	Y	
5 REAR LH BUMPER EXTENSION FILLER X NN	1.00	123.70	30.93	92.77	L	Y	
6 REAR RH BUMPER EXTENSION FILLER X BR	1.00	123.70	30.93	92.77	L	Y	
7 REAR BUMPER CENTER UNDER COVER / CRU	1.00	229.90	57.48	172.42	L	Y	
8 REAR RH BUMPER UNDER COVER X NN	1.00	175.10	43.78	131.32	L	Y	
9 SMART KEY ANTENNA / BR	1.00	72.00	18.00	54.00	L	Y	
10 REAR RH BUMPER SIDE SEAL X NN	1.00	88.50	22.13	66.37	L	Y	
11 REAR BUMPER REINFORCEMENT X NN	1.00	332.70	83.18	249.52	L	Y	
12 REAR BUMPER TOWING COVER / MIS	1.00	15.40	3.85	11.55	L	Y	
13 REAR END PANEL / DD	1.00	650.30	162.58	487.72	L	Y	
14 REAR END PANEL TRIM BOARD / CRU	1.00	126.70	31.68	95.02	L	Y	
15 REAR FLOOR PAN ASSY X NN	1.00	583.40	145.85	437.55	L	Y	
16 REAR RH SIDE FLOOR PANEL EXTENSION X NN	1.00	78.30	19.58	58.72	L	Y	
17 TAILLAMP UPPER RH / BR	1.00	451.80	112.95	338.85	L	Y	
18 TAILLAMP LOWER RH X NN	1.00	502.00	125.50	376.50	L	Y	
19 TAILLAMP PANEL RH X R	1.00	103.40	25.85	77.55	L	Y	
20 TAILLAMP COVER RH / CUT	1.00	64.50	16.13	48.37	L	Y	
21 TAILLAMP UPPER LH X NN	1.00	451.80	112.95	338.85	L	Y	
22 TAILLAMP LOWER LH X NN	1.00	502.00	125.50	376.50	L	Y	
23 REAR TAILGATE PANEL ASSY / BR	1.00	1,147.80	286.95	860.85	L	Y	
24 REAR TAILGATE OUTER GARNISH / BR	1.00	925.60	231.40	694.20	L	Y	
25 REAR TAILGATE TOYOTA EMBLEM / NEC	1.00	47.90	11.98	35.92	L	Y	
26 REAR TAILGATE HYBRID EMBLEM / NEC	1.00	54.60	13.65	40.95	L	Y	
27 REAR TAILGATE PRIUS EMBLEM / NEC	1.00	54.60	13.65	40.95	L	Y	
28 REAR BOOT INNER TRIM BOARD (BIG) / BR	1.00	259.20	64.80	194.40	L	Y	
29 REAR BOOT INNER TRIM BOARD (SMALL) X NN	1.00	225.20	56.30	168.90	L	Y	
30 REAR BOOT LOCK / BT	1.00	467.00	116.75	350.25	L	Y	
31 REAR BOOT WEATHERSTRIP / TN	1.00	372.30	93.08	279.22	L	Y	
32 REAR RH DECK FLOOR BOX X NN	1.00	313.60	78.40	235.20	L	Y	
33 REAR TAILGATE UPPER WINDSCREEN / NEC	1.00	28.90	7.23	21.67	L	Y	
ADHESIVE DAM							
34 REAR TAILGATE UPPER WINDSCREEN / NEC	1.00	35.50	8.88	26.62	L	Y	
MOULDING							
35 REAR TAILGATE LOWER WINDSCREEN / BR	1.00	761.40	190.35	571.05	L	Y	
GLASS							
36 REAR TAILGATE LOWER WINDSCREEN / NEC	1.00	28.90	7.23	21.67	L	Y	
ADHESIVE DAM							
37 REAR TAILGATE LOWER WINDSCREEN / NEC	1.00	23.60	5.90	17.70	L	Y	
MOULDING							
38 REAR LH TAILGATE LOWER WINDSCREEN / NEC	1.00	30.90	7.73	23.17	L	Y	
MOULDING NO.2							
39 REAR RH TAILGATE LOWER WINDSCREEN / NEC	1.00	30.90	7.73	23.17	L	Y	
MOULDING NO.2							
40 REAR SPOILER ASSY X NN	1.00	1,575.40	393.85	1,181.55	L	Y	
41 REAR THIRD BRAKE LAMP X NN	1.00	192.30	48.08	144.22	L	Y	
42 REAR LH DECK FLOOR BOX X NN	1.00	313.00	78.25	234.75	L	Y	
43 SPARE TYRE BOARD / CRU	1.00	519.00	129.75	389.25	L	Y	
44 REAR LH LUGGAGE SIDE TRIM X NN	1.00	355.90	88.98	266.92	L	Y	
45 REAR RH LUGGAGE SIDE TRIM / CRU	1.00	355.90	88.98	266.92	L	Y	
46 REAR BUMPER WIRE HARNESS X NN	1.00	170.70	42.68	128.02	L	Y	
47 REAR BOOT WIRE HARNESS X NN	1.00	294.40	73.60	220.80	L	Y	
48 REAR BUMPER CLIP SET / NEC	1.00	80.00	0.00	80.00	S	Y	
49 REAR REVERSE SENSOR SET / BR	2.00	400.00	0.00	400.00	S	Y	
50 REAR LICENCE PLATE NUMBER WITH / CUT	1.00	100.00	0.00	100.00	S	Y	
FRAME							
51 REAR BUMPER PROTECTOR (chrome) / BT	1.00	160.00	0.00	160.00	S	Y	
52 REAR TAILGATE OUTER GARNISH CLIP SET / NEC	1.00	65.00	0.00	65.00	S	Y	

P- 7974
-25%
5980.50

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
53 REAR TAILGATE "6552-1111" STICKER / <i>AK</i>	1.00	140.00	0.00	140.00	50 S	Y	
54 REAR TAILGATE "COMFORT DELGRO" STICKER / <i>AK</i>	1.00	140.00	0.00	140.00	50 S	Y	
55 REAR TAILGATE "BOOK NOW" STICKER / <i>AK</i>	1.00	140.00	0.00	140.00	50 S	Y	
56 REAR BUMPER UNDER COVER CLIP SET / <i>AK</i>	1.00	65.00	0.00	10 65.00	S	Y	
57 REAR BOOT INNER TRIM BOARD CLIP SET / <i>AK</i>	1.00	65.00	0.00	10 65.00	S	Y	
58 REAR SPOILER CLIP AND PAD SET / <i>AK</i>	1.00	55.00	0.00	10 55.00	S	Y	
59 REAR WINDSCREEN PRIMER / <i>AK</i>	2.00	160.00	0.00	40 160.00	S	Y	
60 REAR WINDSCREEN SEALANT / <i>AK</i>	3.00	180.00	0.00	30 180.00	S	Y	
61 REAR WINDSCREEN GLASS PAD SET / <i>AK</i>	1.00	55.00	0.00	10 55.00	S	Y	
62 REAR LUGGAGE SIDE TRIM CLIP SET / <i>AK</i>	1.00	55.00	0.00	10 55.00	S	Y	
63 TAILLAMP GUIDE CLIP SET / <i>AK</i>	1.00	55.00	0.00	10 55.00	S	Y	
64 REAR BUMPER EXTENSION FILLER CLIP / <i>AK</i>	1.00	55.00	0.00	10 55.00	S	Y	
65 REAR END PANEL SEALANT / <i>AK</i>	2.00	170.00	0.00	20 170.00	S	Y	
66 REAR END PANEL INSULATOR SET / <i>AK</i>	1.00	150.00	0.00	150.00	S	Y	
67 REAR FLOOR PAN SEALANT / <i>AK</i>	2.00	170.00	0.00	170.00	S	Y	
68 REAR BUMPER SIDE SEAL CLIP / <i>AK</i>	1.00	55.00	0.00	55.00	S	Y	
69 REAR BUMPER RETAINER CLIP / <i>AK</i>	1.00	55.00	0.00	55.00	S	Y	
70 REAR END PANEL TRIM BOARD CLIP SET / <i>AK</i>	1.00	55.00	0.00	10 55.00	S	Y	
TOTAL:		17,137.80	628.32	13,509.48			

TOTAL PARTS & LABOUR :

23,837.80 3,628.32 20,209.48

EXCESS/LOADING: S\$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: ____ / ____ / ____

SURVEYED BY: _____

CONTACT NO: _____ FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL: _____

FAX: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

P-5980.50
N-700
L-2350
9030.50
L/S-7224.40
=72.00

MR PL
L/S
By ATL sy
6 days

n-700