



YSK AUTO WORKSHOP

No. 1 Kaki Bukit Avenue 6 @Autobay, #01-71 Singapore 417883
UEN 53311047E

LKK Auto Consultants Pte Ltd

Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1, #02-25 | S(408933)

Tax Invoice : 202201-0005
Date : 10/01/2022
Vehicle : SLD508P
Make Model : MAZDA 3 1500cc
Accident Date : 30/11/2021 14:30 (SGT)
Accident Location: ALONG BEDOK NORTH AVE 3

Particular

COST OF REPAIR & LABOUR	\$2,100.00
LOSS OF USE for 3 Days X @\$120 per day	\$ 360.00
Pre-Repair Inspection for 2 days x @\$120.00 per day	\$ 240.00

Singapore Dollars: Two Thousand Seven Hundred Only

Total S\$: 2,700.00

=====



YSK Auto Workshop