

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	: CS/AGI21012366/Vvf3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Dat	re: 15/12/2021	
			Cod	de: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMM 9862Y	Veh. Inspected	FBQ 1911B	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10012776/CD	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	07/12/2021	
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA AEROX 155	c.c	155	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	MH3SG4640KJ055717	Colour	GREY	
	Odometer	41816 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	120/70 14	ZENEOS	6 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	120/70 14	ZENEOS	6 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.				
	DAMAGES SEE DETAILS.				
5. General Information					
	Accident Date	04/12/2021	Inspection Date	07/12/2021	
	Survey held at ERZAT LEE MOTOR TRADING PTE LTD				
	25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: