



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2200611

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 04/02/2022
Reference CS3/III20012509/Dqf3e2-1
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SMH 9726J
Insured Veh. SHD 3211Y
Claim No. MCT20110205
Policy No. MCOM0015
Accident Date 12/11/2020
Inspection Date 13/11/2020

Description	Total
Survey Inspection	350.00
Digital Photographs	
Transportation	
Less: Pre-Repair Survey Fee (Invoice.AC2007843 dated 20/11/2020)	-120.00
Subtotal	230.00
GST (7%)	16.10
Grand Total	246.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM