

ACRA NUMBER: 200911678H

GST REGISTRATION NUMBER: 2009 1 1678H

6 December 2021

Our Ref: FBN 6801T (K) EB Your Ref: SMS 5719Z DIRECTOR:
RIAZ QAYYUM :LLB HONS: NUS

(ASSOCIA

ABBUIL HALIM BIN ROSALAN (LIB HONS) LITAS

MUHD RIDHWAN ABDUL RAHIM LLB HONSI LEEDS

IRFAN NASRULHAQ BIN HAMDAN ILLB HONSISMU

AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way Tower 2 #07-16 Singapore 079120

Attn: Motor Claims Department

BY EMAIL ONLY

NOTICE OF ACCIDENT

Dear Sirs,

TO:

We are instructed by our client to *notify* you of a road traffic accident on <u>24 November 2021</u> at about <u>0930</u> hours along <u>PIE (Changi) before Steven Road exit</u> involving our client's vehicle registration number <u>FBN 6801T</u> and vehicle registration number <u>SMS 5719Z</u> driven by you or your authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop : EQBH PTE LTD

Address : 25 KAKI BUKIT ROAD 4

#03-79 SYNERGY @ KB SINGAPORE 417800

Telephone no. : 6384 6939/9011 3391 (Wille)

Please let us hear from you by the stipulated time.

FOR SURVEYOR

Please initial here after completion of prerepair inspection. Thank you.

Appointed surveyor (Name & signature)

Date & time of inspection

cc Client

Yours faithfully

Riaz.

