

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE PTE LTD			Ref:	CS3/ASM21012394/Gqy3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	09/02/2022		
	ATTN: OH VALE			Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SH 8288S	Veh. Inspected		JSP 2346	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03NO5	Excess (\$)		0.00	
	Assign From	OH VALE	Assign Date		07/12/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	YAMAHA YZF-R25	c.c		250	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	PMYRG1510J0012721	Colour		BLUE	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	110/70Z R17	PIRELLI		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	150/60Z R17	PIRELLI		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION.					
5.	General Information					
	Accident Date	30/09/2021	Inspect Date / T	ime	08/12/2021 (04:50 PM)	
	Survey held at	EQUATOR BROTHERHOOD				
	25 KAKI BUKIT ROAD 4 #03-79 SYNERGY @KB SINGAPORE 417800					
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		3 Worki	ng Days	

Report Ref No. CS3/ASM21012394/Gqy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.