

CHOON HOCK MOTOR TRADING CO

*Not Notwork
 11 Days @ 1600h
 Repair After Paint
 3 days*

6 December 2021

ESTIMATE REPAIR BILL ON SCW8675T HONDA CIVIC AUTO

1 pce rear lamp LH	<i>Lr</i>	\$ 350.00	✓
1 pce rear lamp lower panel LH	<i>R</i>	\$ 80.00	✓
1 pce rear bumper assy.	<i>Bu</i>	\$ 750.00	✓
1 pce rear bumper retainer LH	<i>br</i>	\$ 75.00	✓
1 pce rear panel	<i>R</i>	\$ 380.00	X
1 pce rear boot logo 'H'	<i>me</i>	\$ 45.00	✓
1 pce 'CIVIC' logo	<i>me</i>	\$ 70.00	✓
1 pce 'VTI' sticker	<i>me</i>	\$ 30.00	✓
		\$1,780.00	
	less 20%	\$ 356.00	
		\$1,424.00	

Labour

Rustproofing	\$ 80.00	<i>200</i>
Wiring	\$ 50.00	<i>200</i>
Panel beating	\$ 900.00	<i>3500</i>
Spray painting	\$ 900.00	<i>5000</i>
Total amount:	\$3,354.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before ~~after~~ spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: