

⏪

⏩

1 of 2 ?

⏮

⏭

100%

📄

🖨

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref: CS3/SMO21008855/Avf3-1	
50 RAFFLES PLACE #03-03			Date: 08/12/2021	
SINGAPORE LAND TOWERSINGAPORE 048623			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 503X		Veh. Inspected	SBZ 2288M
Policy No.	D21MTPCVE001067		Coverage (\$)	0.00
Claim No.	CMTD2102521/RUC		Excess (\$)	0.00
Assign From	RUTH CHUA GEK TIANG		Assign Date	08/12/2021
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/08/2021		Inspection Date	
Survey held at	GARAGE 13 PTE LTD			
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				