	The second secon	
—	CS ALS 210	12/12/17 13
s. FEN:	-C2 N12510	12430 DVJ3
* ***	ASSIGN	
DITT:	Date: V	en No: SMP 3698 D YT REST! Jan 12010
sirna Cost		yperM.Ca / M.Cycle / Bus / Van / Lorry Taxi / Prime Mover /
	RES I OD RES I EVA I INV I MV	Truck/Trailer or
o Inspatiehide	No:	inte: Maserati Grandturismes 4691
Work to mis		Colour White . AIC: Insured Still PRI NA
Water and a second	 , 	
f	•	opa watering 25.15
		Eng/No:- M145154982
olicy Et		CANO: ZAMHH 458000050413
Claires b 2	021 20003071fq	Gen. Cond: 6000 Fair Poor Burni
Sum Ir sandi	Excess: 15,000	Steering: in order / Jammed / Leaked / Burnit or
(Chezislecon	ŋ ·	Brake: Indirector / Jammed / Leaked / Burnt or
Wake alver		Mod: NEI / SROm / STD A/Rim or
		Tyre Size: F: 245 35 7.20
(Policy Condition		R 285 35 R 20
	n had commenced its N/S O/S	BS DUN EXNOVA GY FS LIZA MIC OHTSU PIR SUMA
	at the time of inspection.	TOYOTYOKO OF Condinand
Bal of Malest Va		Front
IDAC Accient R		R/Bal R/Bal man
GIA / PR Seen		L/Bal S mm
Est Repais	30 % 3 Val.: Yes or No	D.O.A. 11 11 2021 D.O.L. 09 12 221
Lim-Sum	30 % 3 Val.: Yes or No	Survey held at JWG AMK
CA / REV /	REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages: Frt Rear O/S N/S U/C Rooftop of
Date;	Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date /Time	Action / Instruction	
	Alliany OD	
	- No in	odificating. 4 Tyles in serviceable and
	MY 150K - Mangu	of accident suggest to carry but
	LTA 32K interior	new.
100	NL 118K - Repair	or proposed to repair at contract sum
	- Pendi	of per price dede.
10/0/00		10, 404,00, 700/
10/8/22	Bryan informed LS \$80,000 (Red 2	18, 124.83, 73%)
Date/Time, File Pa	: Prefi. Report	Days Of Repair: 20
43	Final Report	Resurvey No. of Trip: 2 Survey Feet
CeleTate, File R	tet_; <u>=</u> ?	Transportations
2 10/8/22	41 //4 / 44	ee: : Site insp (\$)_3+R3_31

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	553D
Vehicle No.:	SMP3698D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Nov 2021
Vehicle Make:	MASERATI
Vehicle Model:	GRANTURISMO S 4.7 A
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	M145154982
Chassis No.:	ZAMHH45B000050413
Maximum Power Output:	323.0 kW (433 bhp)
Open Market Value:	\$127,069.00
Original Registration Date:	08 Jan 2010
First Registration Date:	08 Jan 2010
Transfer Count:	5
Actual ARF Paid: Intended PARF Rebate Details	\$127,069.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	07 Jan 2030
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$39,463.00
COE Rebate Amount:	\$32,175.00
Total Rebate Amount:	\$32,175.00

The information contained herein is correct as at 12 Nov 2021

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources





Mercedes-Benz GLE-Class Coupe

The bigger brother of the GLC. Bigger, Better, Badder. Attractive savings Guaranteed.

Post an Advertisement Sell it yourself! Advertise it at just \$68 until it's SOLD! 2016 Kia Carens Diesel 1.7A SX Sunroof At \$66.5k.



Trust Motoring StarAd



Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

~

Make

Maserati GranTurismo 4.7

Model

Sort by Date Posted Advanced Search

✓ 20 results/page ✓

12 vehicles

Reg Date

Eng Cap Mileage

Search Selection

Maserati GranTurismo 4.7

Апу

\$162,888

Price

Any

Depreciation

Anv

Anv

Maserati GranTurismo S 4.7A (COE till 04/2029)

\$21,810 /vr

08-Dec-2009

4,691 cc

90,000 km

Sports

Veh Type

Available

Available

Tridente Maintained & Serviced With Records. One of The Best Sounding V8 Ever Made. Equipped With All Time Reliable ZF Gearbox. No Messy Modifications. Loans & Trade-In Packages Available. Call / WhatsApp Us For More Info

PREMIUM AD

03/2031)

Posted: 04-Nov-2021 Tags: 2009 Maserati GranTurismo, Maserati GranTurismo, Maserati, GranTurismo



Maserati GranTurismo S MC \$185,000 \$19,800 /yr Sport Line 4.7A (COE till

16-Mar-2011

4,691 cc

86,000 km

Available Sports

Rarest! Best MC Sportline Around! Lightly Used 2nd Car. New Phantom Grey Wrap And Original Carbon Fibre Package And Alcantara Interior Trim! Tri-Color Brake Calipers. Fully Done Up! Definite Head Turner! Regularly Maintained With Wear And Tear All Done Up Rece...

DIRECT OWNER

Posted: 05-Nov-2021 Tags: 2011 Maserati GranTurismo, Maserati GranTurismo, Maserati, GranTurismo



Maserati GranTurismo MC Stradale 4.7A (COE till

\$215,000 \$22,020 /yr

16-Aug-2011

4,691 cc

93,270 km

Sports

Available

PREMIUM AD

08/2031) Less Then 15 Units Avail In Sg. Will Be Collector Soon Once It Hit Below 10, Flexible Bank/In House Loan Available! Welcome Trade-In, Book An Appointment With Our Staff Now For Viewing!

Allmotoring.sa

Posted: 30-Oct-2021 Tags: 2011 Maserati GranTurismo, Maserati GranTurismo, Maserati, GranTurismo



Maserati GranTurismo MC Stradale 4.7A (New 10-yr

\$238,888 \$23,880 /yr

14-Oct-2011

4,691 ∞

78,000 km

Sports

Available

COE) One & Only Full Spec MC Stradale Fitted With Ferrari Enzo Seats From Maserati Italy And Not Forgetting It's Factory Fitted Maserati Roll Cage Coupled With Professional Racing 4 Point Seat Belts! RACE Button Turns Carbon Into Beastly Exhaust Note! Car Park Under Shelter...

DIRECT OWNER

Posted: 02-Oct-2021 Tags: 2011 Maserati GranTurismo, Maserati GranTurismo, Maserati, GranTurismo



Lenovo Multimedia Set & Free Car Vacuum Deal

Upgrade to Lenovo Smart Android 6+128GB@4G Multimedia player for seamless navigation and entertainment in your car

Find out more



Maserati GranTurismo S 4.7A \$198,000 (New 10-yr COE)

\$19,790 /yr

14-Mar-2012

4.691 cc

78,000 km

Sports

Available

Well Taken Care By Owner With New Coe. Flexible Loans Available. A Car Not To Be Missed. Call Today Or Lose The Chance To Own One Of The Finest Examples In The Market.

PREMIUM AD

Posted: 09-Nov-2021 Tags: 2012 Maserati GranTurismo, Maserati GranTurismo, Maserati, GranTurismo



Maserati GranTurismo MC Stradale 4.7A (New 10-yr

F1 Auto Cars Pte Ltd

\$258,888

\$25,870 /yr

30-Mar-2012

4,691 cc

45,000 km

Sports

Available

COE) All Stocks! Low Mileage! Well Maintained Fully Service And Maintained By Professional Workshop. Viewing By Appointment Only.

Tags: 2012 Maserati GranTurismo, Maserati GranTurismo, Maserati, GranTurismo

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

- policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident**

Additional Location Information Country/State of Loss

12/11/2021 19:48 (SGT) 11/11/2021 01:55 (SGT)

Singapore PIE

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMP3698D

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

Email Address

Mobile Phone No

Alternative Phone No

CHEN KAILIN

S9174553D

chen_kailin@hotmail.com

(Phone) +65-96715658

+65-96715658

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

CC

Maserati

GRANTURISMO

Private use

Yes

Private car

Auto

4700

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy

Policy Number

Cover Note Number

Allianz Insurance Singapore Pte. Ltd.

Comprehensive

No

SP2000075596

04/11/2020 - 07/01/2022

DRIVER

Name of Driver

NRIC No

CHEN KAILIN S9174553D



Date Of Birth Occupation

Date Of Driving Pass Driving experience

Gender

Mobile Number Alt. Phone Number

Email Address Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

19/04/1991 Indoor

08/03/2013

8 YEARS AND 8 MONTHS

Male

(Phone) +65-96715658

+65-96715658

chen_kailin@hotmail.com

BLK 439B BUKIT BATOK WEST AVE 6 #14-971

652439

Yes

No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Side Swipe DRIZZLING Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

PASSENGER 1

Name

Gender

No

2

No

Yes

2

No

ANG YIZHEN SHERMAINE

Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Police Station Name Police Station Phone No

Alt. Police Station Phone No. Police Station Address

Was notice of intended Prosecution given?

If yes, against whom?

Clementi Neighbourhood Police Centre

(Phone) +65-18008729999

(Fax) +65-68728039 No. Singapore 129858

No

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Was there any audio recorded?

Yes

No

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer

SLS828L



Vehicle Model	-
Vehicle Variant	8
Vehicle Colour	+
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

- SMP 3698D (Allianz) DOA: 11/11/21@0155
- Rease report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

& Time

- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Skinature (# driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel OV VI AWK

Sketch Plan

AB TO THE PROPERTY OF

vehicle A- smp36980 vehicle B- S16838L

	on the	c stated	date a	and ti	me,	١,	vehicle	A	(sm	P 3698	D)	was tra	velling
straight	at the	stated	le cotion	on the	extr	eme	right l	ane.	suc	denly	mu	vehicle	Skidded
to the	1984 and	collided	buto	veloide 8	sl sisb	(18<	, There	after	mu	vehicle	(ont	ique to	skid
o the	fencing	on the	right	and t	ary 3	00 d	gree.		collided	onto	the	tencing	of the Pil
	I	prefered	tri Diuc	oma tion	al Pte	Ltd	to tepai	ir M	y Vehic	le -			
											-		
					-					*			
_								_					
					-	-		-					
				-				7			-		
											-		
			-										
			73			21							-
									- 100				
	The state of the s									7			

Declaration

I'We declare the foregoing particulars are true in every respect.

4

Policyholder's Signature / Date & Time

4

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (AMK)



REPORT OF A TRAFFIC ACCIDENT



Report No. T/20211111/2005

Police Station Of Origin: Clementi N.P.C 20 Clementi Avenue 5 SINGAPORE 129858 Tel No: 1800-8729999

Station Diary No. Vide Report No : Date/Time Report Made 11/11/2021 04:24 Informant's Particulars Name of Informant. APT BLK 439B BUKIT BATOK WEST AVENUE 8 #14-971 Address: CHEN KAILIN SINGAPORE 652439 Contact No.: ID Type / ID No .: Mobile: 96715658 Home/Office: NRIC NO / S9174553D Email: Nationality SINGAPORE CITIZEN

Date of Birth: Type of Informant: Sex Age: 19/04/1991 Driver 30 Male Institution / School Name: Language: Race: English Chinese Driving Licence Information: Occupation: Date of Expiry: Class: 3 INTERIOR DESGINER

General Information of the Accident Type of Location: Date/Time of Drink Non-Injury Straight Road Type of Accident: Attended by Police Drive: 11/11/2021 02:10 Accident: Location:

PAN-ISLAND EXPRESSWAY

Lamp Post Number 1028 Road Speed Limit: Road Surface: Weather: 70 Km/h Wet Drizzling Traffic Volume: Traffic Control: Traffic Flow: Traffic Light - Working Light One Way Anyone conveyed by Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction ambulance: No

Details of V	ehicle Involv		Mary Comment	Calles	On a dittor	No of Deccondor
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLS828L	Car	FORD	MUSTANG 2.3 GTDI AT	Orange	Slightly Damaged	0
SMP3698D	Car	MASERATI	GRANTURIS MO S 4.7 A	White	Seriously Damaged	1

Details of At	ehicle Insurance	The second of the second of the second	THE AREA	
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMP3698D	ALLIANZ INSURANCE SINGAPORE	SP2000053324	04/11/2020	07/01/2022



Report No. T/20211111/2005

Police Station Of Origin: Clementi N.P.C 20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999

CONTINUATION OF REPORT

Brief Details.

On 11/11/2021 at about 0208hrs I was driving along PIE towards Tuas my vehicle bearing register number: SMP3698D, suddenly my vehicle skid and collided on the side of the vehicle bearing register number: SLS 828L. Thereafter I collided onto the fencing of the PIE. There was no one injury. My vehicle rear was seriously damaged and back wheel suspension seriously damaged. TP was at scene and issued an case card ref to E/20211111/0019. Both parties have exchange particular for insurance claim. I here to lodge report under the instruction of Traffic Police.





Police Station Of Origin: Clementi N.P.C 20 Clementi Avenue 5 SINGAPORE 129858 Tel No: 1800-8729999 Report No. 1/20211111/2005

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

CONTINUATION OF REPORT

Signature Of Informant
Date/Time: 11/11/2021 04:24
Classification Of Case:
BINGAPORE POLICE FORCE SN 37

SIGNATURE

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592 E-Mail: jwg.claims@yahoo.com

To:

ALLIANZ INSURANCE SINGAPORE PTE LTD

Att:

Motor Claims Dept

ACCIDENT INVOLVING SMP3698D [YOUR INSURED] & SLS828L [THIRD PARTY] ON 11/11/2021.

ESTIMATED REPAIR COSTS FOR SMP3698D

QTY	PARTS	A	MOUNT	
1PC	BONNET Buc	\$	8,974.00	ı
2PCS	BONNET HINGE LH / RH @ \$390.00 EACH 54	\$	780.00	1
2PCS	BONNET DAMPER LH / RH @ \$891.00 EACH SVL	\$	1,782.00	1
1PC	BONNET LOCK Dan	\$	692.00	_
1PC	BONNET STRIKER LOCK 5+	\$	241.00	
1PC	BONNET LOCK CABLE	\$	903.00	
1PC	BONNET INSULATOR TOWN 458.00	\$	1,598.00	-
1PC	BONNET SEAL MF 4331.00 X 2	\$	398.00	-
2PCS	HEAD LAMP LH / RH @ \$10,498.00 EACH O S distort m/s broken		20,996.00	-
2PCS	HEAD LAMP LOWER BRACKET LH / RH @ \$461.00 EACH Dead 144	\$	922.00	_
2PCS	HEAD LAMP CONTROL MODULE LH / RH @ \$4,982.00 EACH ≯ ►NA	\$	9,964.00	
2PCS	HEAD LAMP NOZZLE LH / RH @ \$1,298.00 EACH	\$	2,596.00	
1PC	HEAD LAMP NOZZLE TUBE COMPLETE disladge.	\$	2,845.00	
1PC	HEAD LAMP WIREHARNESS COMPLETE ₹ NAC	\$	8,924.00	_
1PC	FRONT BUMPER distorbed 5373.00	\$	7,329.00	-
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$429.00 EACH	\$	858.00	-
2PCS	FRONT BUMPER NOZZLE CAP LH / RH @ \$289.10 EACH - HS	\$	578.20	-
1PC	FRONT BUMPER LOGO distrayed 78.54	\$	298.00	\neg
1PC	FRONT BUMPER GRILLE distaly	\$	1,492.40	
1PC	FRONT BUMPER GRILLE LOGO distribution	\$	314.00	-
1PC	FRONT BUMPER GRILLE INNER COWLING Sooken	\$	1,399.00	_
1PC	FRONT BUMPER GRILLE COWLING SEAL A Shilad put	\$	496.00	-
1PC	FRONT BUMPER NO. PLATE BASE dislosal	\$	250.00	-
1PC	FRONT BUMPER LOWER GRILLE HS	S	894.00	-
2PCS	FRONT BUMPER SIDE GRILLE LH / RH @ \$598.00 EACH distoded	S	1,196.00	-
2PCS	FRONT BUMPER SIDE GARNISH LH / RH @ \$491.00 EACH NS	\$	982.00	-
2PCS	FRONT BUMPER FOG LAMP LH / RH @ \$980.00 EACH HS	\$	1,960.00	-
2PCS	FRONT BUMPER FOG LAMP GARNISH LH / RH @ \$585.00 EACH MS	15	1,170.00	_
6PCS	FRONT BUMPER SENSOR @ \$452.00 EACH	\$	2,712.00	$\overline{}$
1SET	FRONT BUMPER SENSOR HOLDER on should yet	\$	120.00	

4130 94

AMOUNT

1PC	FRONT BUMPER SENSOR WIREHARNESS Z N-4	\$	4,985.00
1PC	FRONT BUMPER SPONGE oholoden	\$	592.00
IPC IPC	FRONT REINFORCEMENT BAR TOP	\$	1,592.00
	FRONT REINFORCEMENT BAR LOWER disluction	\$	1,629.00
PC	FRONT SUPPORT PANEL & disted &	S	4,895.00
PC	FRONT SUPPORT PANEL TOP GARNISH bales I showed	\$	489.00
PC	FRONT SUPPORT PANEL FOR GARNISH LH / RH @ \$419.00 EACH	\$	838.00
PCS		\$	904.00
PC	FRONT BRACE TAILED STATES	\$	1,890.50
PC	TROIT BOTT ORT THE POT CO. 221	\$	1,488.10
PC	TRONT ARCHITARE BEET COM 2212	\$	2,459.00
PC	A/C CONDENSOR HIGH PRESSURE PIPE 151 C->	\$	1,398.00
PC	AC COMBENSOR MONTHESS STEET	\$	783.00
PC	THE CONDENSOR DO IT THE DESCRIPTION OF THE PROPERTY OF THE PRO	\$	2,845.10
PC	RADIATOR ASSY 1/2+	\$	824.00
PC	TOTAL TOTAL TOTAL	\$	334.00
PC_	RADIATOR FAN BLADE HA	\$	678.00
PC	OIL COOLER ASSY 134	\$	3,001.00
PC		\$	4,980.00
PCS	FRONT FENDER LH / RH @ \$2,490.00 EACH FRONT FENDER INNER SHIELD LH / RH @ \$510.00 EACH From	-	1,020.00
PCS		\$	410.90
PC	FRONT FENDER LAMP LH boxes	\$	720.00
BPCS	FRONT FENDER GRILLE LH @ \$240.00 EACH LZ dwlody 17cHu	\$	1,982.40
PC	FRONT WHEEL HOUSING LH	\$	1,882.40
PC	ROCKER PANEL GARNISH LH baken	\$	1,784.00
PC	ROCKER PANEL LH HW	\$	
PC	FRONT DOOR LH	\$	8,028.50 529.00
PC	FRONT DOOR WEATHER STRIP LH 9V2	\$	402.00
2PCS	FRONT DOOR HINGE LH @ \$201.00 EACH	\$	399.00
IPC	FRONT DOOR WINDOW MOULDING LH	-	
IPC	FRONT DOOR INNER TRIM BOARD LH Broken	3	2,982.40 13,848.00
2PCS	FRONT RIM LH / RH @ \$6,924.00 EACH O S HA CH O		1,784.00
2PCS	FRONT WHEEL BEARING & HUB ASSY LH / RH @ \$892.00 EACH Dex	\$	2,784.00
2PCS	FRONT KNUCKLE ARM LH / RH @ \$1,892.00 EACH	9	3,784.00 2,184.80
2PCS	FRONT LOWER ARM LH / RH @ \$1,092.40 EACH of strong	\$	7.5 Value 10 (1822-1922)
2PCS	FRONT ABSORBER LH / RH @ \$1,789.00 EACH distract	\$	3,378.00
2PCS	FRONT UPPER ARM LH / RH @ \$1,459.00 EACH		2,918.00 2,796.00
2PCS	FRONT THRUST ARM LH / RH @ \$1,398.00 EACH		
2PCS	FRONT STABILIZER LINK LH / RH @ \$410.00 EACH ₩	S	820.00
PC	FRONT STABILIZER BAR	S	1,675.00
1PC	STEERING RACK & PINION ASSY	\$	
1PC	REAR FENDER LH	_	17,829.40
1PC	REAR FENDER INNER SHIELD LH * SIL	\$	452.00
1PC	REAR FENDER INNER PANEL LH	\$	9,845.10
1PC	REAR FENDER LOGO LH Hac	\$	294.00
1PC	REAR BUMPER Au	\$	7,298.00
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$398.00 EACH	\$	796.00

1PC	REAR RIM LH Cwt	\$	6,924.00	1
1PC	REAR WHEEL BEARING & HUB ASSY LH 2 Days	\$	984.00	-
1PC	REAR KNUCKLE ARM LH ? distor	\$	1,894.00	
1PC	REAR LOWER ARM LH Z distance	\$	1,392.00	-
1PC	REAR CONTROL ARM LH Z district	\$	1,094.00	
1PC	REAR UPPER ARM LH % disture	\$	1,592.00	-
1PC	REAR ABSORBER LH Ze disturbi	\$	1,890.00	-
1PC	REAR STABILIZER LINK LH Z HAL	\$	390.00	-
1PC	REAR STABILIZER BAR 2 HALL	\$	1,771.00	
1PC	REAR CROSSMEMBER 7 HM	\$	6,019.00	
1PC	REAR DIFFERENTIAL HA		15,920.00	
1PC	REAR DRIVE SHAFT LH HAT distribut	_	13,994.00	
1PC	REAR WINDSCREEN HH		10,942.00	- /
1PC	FRONT DOOR AIR BAG LH activated	\$	3,985.00	-
1PC	FRONT PASSENGER SEAT and tom	\$	- 1	-
1PC	FRONT PASSENGER SEAT AIR BAG LH adval	\$	4,012.00	-
1PC	SRS CONTROL MODULE Den	\$	5,001.00	
	148040-64 51691 W PARTS SUM: PARTS LESS 10%: PARTS TOTAL:			
	PARTS TOTAL:			
	1770			

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY 3PCS TYRE	\$	3,000.00 ×
*	TO SUPPLY BONNET INSULATOR CLIPS Hec	\$	50.00 10 -
*	TO SUPPLY HEAD LAMP CLIPS HH	\$	50.00 >
*	TO SUPPLY FRONT BUMPER CLIPS HIGH	\$	50.00 201-
*	TO SUPPLY FRONT GRILLE CLIPS +46	\$	50.00 10 1-
*	TO SUPPLY FRONT BUMPER LOWER GRILLE CLIPS 43	\$	50.00 ×
*	TO SUPPLY COOLANT HH	\$	200.00 ×
*	TO SUPPLY FRONT SUPPORT PANEL TOP COVER CLIPS HEE HA	\$	50.00-151= X
*	TO SUPPLY FRONT SUPPOER PANEL TOP GARNISH CLIPS	\$	50.00 * 151-
*	TO SUPPLY FRONT FENDER INNER SHIELD CLIPS	S	50.00 201-
*	TO SUPPLY ROCKER PANEL GARNISH CLIPS HIG	\$	50.00201-
*	TO SUPPLY ROCKER PANEL SEALANT HH	\$	100.00 ×
*	TO SUPPLY REAR BUMPER CLIPS HA	\$	50.00 ×
*	TO SUPPLY REAR FENDER SEALANT HH	\$	100.00 >
*	TO SUPPLY REAR FENDER INNER SHIELD CLIPS * VI	\$	50.00 AX
*	TO SUPPLY REAR WINDSCREEN SEALANT HH	\$	100.00 >
*	TO SUPPLY REAR WINDSCREEN DAMPING SEAL HA	S	50.00 ×
*	TO SUPPLY FRONT DOOR INNER TRIM CLIPS HAC	S	50.00
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE	\$	600.00 100 -
	REPAIRS		

*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 6,000.00 1600 -
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 6,000:00 1600 -
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00 40 -
*	TO RNR A/C CONDENSOR TO FACILITATE REPAIRS	\$ 300.00 100 -
*	TO RNR RADIATOR ASSY TO FACILITATE REPAIRS	\$ 300.00
*	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 400.00 \$250 -
**	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 400.00 240 -
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	\$ 120.00 60 -
*	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	\$ 250.00 HH
*	TO RNR REAR CROSSMEMBER TO FACILITATE REPAIRS	\$ 300.00 нн
*	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS 4430 W	\$ 500.00 HH
*	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	\$ 120.00 HH
*	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	\$ 150.00 버버
*	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	\$ 300.00 ₩M
*	TO RNR FRONT PASSENGER SEAT TO FACILITATE REPAIRS	\$ 200.00 60 -
*	TO RNR ACTIVATED AIRBAGS TO FACILITATE REPAIRS	\$ 600.007 1801-
*	TO RNR SRS CONTROL MODULE TO FACILITATE REPAIRS	\$ 500.00
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00 30 -
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 1,000:00 150 -
	13 7 781-57 LABOUR & S/N TOTAL:	\$ 22,690.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 298,124.83

GRAND TOTAL ESTEMATED AND 100 12/2021 @ 1000m 20 12/2021 @ 1000m 20 12 days

Tyan Exuss TBA.

LKK AND MV 150K

LTA 32K

HL 118K

LKK Auto Consultants hence notify

- the Repairer of the following: To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: