Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)

Sent: Monday, 17 January 2022 11:52 AM

To: EDWIN KANG WEE HUAT

Cc: HO AIK SENG, DENNIS; RISHABH RADHAKRISHNAN; Jaslin Kok (LKK Auto); Olivia

Lau (LKKAuto)

Subject: IOD: CY 20/21/0030 // LKK Ref: CC2/MIDA21012437/p [ACCIDENT INVOLVING

MID34081 AND YP6256J ON 31/07/2020]

Attachments: Correspondence Email with Third Party.pdf; FINAL COST OF REPAIR MID34081

KHATIB CSW.pdf

Dear Maj Edwin,

We refer to the above matter.

SAF driver reported that his vehicle rolled backwards and hit onto civilian lorry (YP6256J). As such, we are of the view that SAF driver is at fault.

We suggest to close file due to the following reason: -

- 1. Third party is not pursuing the claim. Pls refer to attached correspondence email with third party.
- 2. MID FCOR is \$56.38. TCA is applicable each party should bear its own loss.

Kindly let us have your approval/instruction.

"Wishing You Happiness & Prosperity Chinese New Year 2022"

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com |

HQ: Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

From: HO AIK SENG, DENNIS < HO Aik Seng Dennis@defence.gov.sg>

Sent: Wednesday, 5 January 2022 3:51 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: RISHABH RADHAKRISHNAN < Rishabh_Radhakrishnan@defence.gov.sg>; EDWIN KANG WEE HUAT

<KANG_Wee_Huat_Edwin@defence.gov.sg>

Subject: FCOR for MID 34081

Dear Hisao Tong,

The attached is the corrected FCOR for MID 34081.

Pls note for filling and follow up if required.

Regards,

DENNIS HO
TA INVESTIGATION WO
HQ TPT/ SAFETY BR
63074511
91763064

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorised person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."