



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Ref: CS/CTI21012438/T1vy3

Date: 08/12/2021

Code: CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBL 1944H	Veh. Inspected	SJG 5759G
Policy No.	DMCVSNA00049442101	Coverage (\$)	0.00
Claim No.	SNM21D207070/C02/LEWLC	Excess (\$)	0.00
Assign From	JENNY LEW	Assign Date	08/12/2021

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/12/2021	Inspection Date	09/12/2021
Survey held at	1 Kaki Bukit Avenue 6 #01-08 Autobay@Kaki Bukit		
Repairer	TSL AUTO GARAGE		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.