Our Job Ref No 305496784					LINUINEERINU		
Date	: _		14/12/2021		ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969		
FINA	ALIZATION FOR	RM			F	ax: 6546 8156	
То	To : LKK				Fax	:	
Attn	:	THEVAN					
	:	SHD6775	S		SH	HA05/12/21	
The	survey and estin	nates of the	epairs of the	above-mentior	ned vehicle are	as follows:-	
1.	The repair job shall bill to:			NTUC		SCM5353B	
2.	The finalized amount shall be:						
	(a) Spare Parts after List discount						
		Charges					
	Total for Part-By-Part Repair Cost						
	(c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after L Final Lumpsum Repair cost				6	\$12,700.00	
 4. 5. 	We shall treat within 7 worki Thank you for y	the above a ng days	mount as Co	rrect and Con		e is no reply from you	
0.	mank you for y	our assistan	isistance.		We confirm the estimates and finalized amount		
	Signature :	Λ	_ s	gnature:	M		
	Name : JUMANI			Name : THEVAN			
	Tel : <u>6214 8315</u>				Date :		
I	Fax : <u>65</u>	468156	\	_			
For Off	icial Use Only	<u></u>					
	Item		Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
1. Rent	. Rental Rate P/Day			YES			
2. Loss	of Income Paid	1	•	N			
3. Surv	. Survey Fees		-	-			
5. Medi of dri	Search Fee cal Fees (on be ver, if applicable	half	.49 / 2.00	YES			
6 Over	iuit						
Remarks	s:						

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

MAKE

SHD6775S

MERC

DATE:

06.12.21

MVA JUMANI

NTUC (LISUM) 12. May. 2021 MODEL **E6** DOA: Amount **Unit Price** Parts Description/Labour Qty Type Ś996.08 XXX 1 FRT FENDER RH M [/]\$2.970.00 1 FRT DOOR RH DT MAKE **/**\$2,870.00 1REAR DOOR RH DT JAMAY **∦\$2,980.00** 1 REAR FENDER RH 1 ADD TU X\$1,510.00 1 REAR BUMPER ASSY \$1,250.00 1 WHEEL RIM FRT RH **/\$1,250.00** 1 WHEEL RIM REAR RH /\$890.00 1|SIDE MIRROR ASSY RH √\$380.00 1SIDE MIRROR GLASS RH 5 **\$350.00** 1 SIDE MIRROR COVER RH CUF /\$920.00 SIDE MIRROR MOTOR RH \$16,366.08 **SUB TOTAL LESS 20%** \$3,273.21 **DISCOUNTED TOTAL** \$13.092.87 LKK Auto Consultants Hence notify the Repairer of the following: ^{N N} × \$50.00 | NET REAR BUMPER MAT To resurvey before/after spray painting To display damaged part(s) during resurvey /\$80.00 NET REAR DOOR COMFORT LOGO Parts prices are subject to confirmation \$80.00 NET REAR DOOR LIMO CAB LOGO Third party survey is on a "Without Prejudice" basis nec /\$46.00 WINDSCREEN SEALANT No illegal modification(s) is allowed Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company \$256.00 Acknowledged by Repairer Signature: Labour Charge Date: PANEL BEATING \$2,400.00 2000 (BONNOT) SPRAY PAINT \$1,800.00 | 500 REMOVE / REFIX REVERSE SÉNSOR \$50.00 20 \$50.00 20 **CHECK WIRING** TUFF KOTE \$50.00 20 REMOVE/REFIX REAR WINDSCREEN GLASS \$120.00 REAR/REFIX UPHOLSTERY REAR \$120.00 Theran Clhhautolom TOTAL LABOUR

2235769 ESTIMATE TOTAL

6/12/1/545

1/5 9fth repair plusto \$4,590.00 \$17,938.87 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.