

Our Job Ref No : 305497043
Date : 08/12/21

ENGINEERING
ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHA 451G

Date of Accident : 05/12/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- AJ 890H

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges (include advertisement sticker etc)

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$1,400.00

Final Lumpsum Repair cost \$1,400.00


3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : THEVAN

Tel : 62148398

Date : 9/12/21

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-Thevan

INSURANCE: NTUC - 4SDATE: 6-Dec-21MODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHA 451G - CityCab ✓

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Rear Bumper	1		\$459.40	✓ cut
	Rear Bumper Centre Moulding	1		\$451.25	✓ scr
	Rear Bumper Side Retainer RH	1		\$55.80	✓ ncc
	Rear Bumper Cover Clips	10	\$2.20	\$22.00	✓ ncc
	Rear Bumper Reflector RH	1		\$41.45	✓ scr
	SUB TOTAL			\$1,029.90	✓
	LESS 20%			\$205.98	
	DISCOUNTED TOTAL			\$823.92	
	Rear Bumper Mat	1		\$50.00	✓ ncc
	NETT TOTAL			\$50.00	
	SPARE PARTS TOTAL			\$873.92	
	<u>Labour Charge</u>				
	Panel Beating			\$400.00	360 x 350
	Spray Painting Charge - Rear Fender RH			\$600.00	500
	R/I Reverse Sensors			\$120.00	30
	TOTAL LABOUR			\$1,120.00	✓
	ESTIMATE TOTAL			\$1,993.92	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

F: 1400

Thevan@lkhauto.com

82235769

6/12/21 1700

L/s after repair photo

2 clay sup ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: