## SIN YU SIN WORKSHOP

#### 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9199 3103/9653 3103

Email: sinyusin@hotmail.com

#### AIG Asia Pacific Insurance Pte Ltd

Motor Claims Department No. 78 Shenton Way #07-16 AIG Building Singapore 079120

Date: 12 January 2022

#### **Letter Of Demand**

Without Prejudice

Re: ACCIDENT INVOLVING GBE2591Y & GBH1496E ALONG AYE CLEMENTI AVE 2 ON 07 DECEMBER 2021

Vehicle No:

GBE2591Y

Vehicle Model:

TOYOTA HIACE

Chassis No:

JTFHT02P300180330

Refer to the above matter.

We hereby offer as below in quantum

 1. Repair Cost
 : \$5,300

 2. Loss of use 08 Day
 : @\$80
 \$640

 4. LTA/TP search
 : \$7.45

Total: \$5,947.45

We hereby enclosed the documents for your necessary action:

Sin Yu Sin Workshop

# SIN YU SIN WORKSHOP

53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883 Mobile no: (65) 91993103/ 97825292Fax: (65) 68163103

## **LETTER OF AUTHORITY**

To: M/S Singapore
Accident involving my/our vehicle no. GBE 25914 and  GBH 1496 E on 57(12(2021
along AYE CLEMENTI AVE 2
I/We, HI-POWER INDUSTRIES PIE LOD NRIC NO. 1990613922
the registered owner of vehicle no. 686 259 (T at the material time of accident, do
hereby authorise "SIN YU SIN WORKSHOP" as my/our agent and representative to
correspond in, negotiate and settle, on my/our behalf, my/our claim against you as
owner/operator/insurer of vehicle no. <u>Свы 1496</u> .
I/We also authorise them to accept settlement cheque on my/our behalf. Kindly issue
your cheque in favour of "SIN YU SIN WORKSHOP".
Dated this OF day of DECEMBER 20 21
ON PIN STATE OF THE STATE OF TH
Kartes

Company's Stamp (For Firm)

Signature of Owner

# SIN YU SIN WORKSHOP

#### 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103/97825292 Fax: 68163103

Email: sinyusin@hotmail.com

#### AIG Asia Pacific Insurance Pte Ltd

Motor Claims Department No. 78 Shenton Way #07-16 AIG Building Singapore 079120

Date: 12 January 2022

#### Re: Final Repair Bill.

Vehicle No:

GBE2591Y

Vehicle Model:

TOYOTA HIACE

Chassis No:

JTFHT02P300180330

<u>ltem</u>	Qty	<u>Price</u>	
1. Lump Sum Repair	1	\$ 5,300	
	Total:	\$ 5,300	

Sin Yu Sin Workshop

### > Back to OneMotoring



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

07 Dec 2021 / 16:43:43

Receipt Date/Time: 07 Dec 2021 / 16:43:43

### Tax Invoice/Receipt

Receipt No.: ITNET-00000-211207-003007

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.  Result of Insurance Enquiry - GBH1496E As at 07 Dec 2021/09:00:00 Insurance Co: AIG ASIA PACIFIC INSURA	NCE PTE. LTD.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
1 Insurance Enquiry - GBH1496E Enquiry Fee 20211207164258247129		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	558860XXXXXX4360	eNETS C	redit Card	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

### THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.