



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623		Ref: CS/SMO21012463/Kqf3e2 Date: 04/01/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBE 4531H	Veh. Inspected	SJD 5877P
Policy No.	D21MTPV01011458	Coverage (\$)	0.00
Claim No.	CMTD2103622	Excess (\$)	0.00
Assign From	AGNES CHAN SHU HUI	Assign Date	09/12/2021
2. Vehicle Particulars & Condition			
Make & Model	SUBARU IMPREZA WRX (A)	c.c	2457
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JF1GHEKD38G010337	Colour	METALLIC PEARL WHITE
Odometer	375619 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/35 R18	GOODYEAR	4 mm
L/H Front Tyre	255/35 R18	GOODYEAR	4 mm
R/H Rear Tyre	255/35 R18	GOODYEAR	4 mm
L/H Rear Tyre	255/35 R18	GOODYEAR	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/12/2021	Inspection Date	09/12/2021
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	