



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV14075/BALZEREIT MARCUS
	Reg No/Reg Date	SMZ4499C / 28/04/202
	Date In/Mileage	/ 0
	Chassis No	KNARH81BVM5038656
	Engine No	D4HELH240632
	Make/Model	KIA/SORENTO 2.2 A D SX SR G704 TECH
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	09/12/2021/ 09:15	BLE	261 / Edwin Caina	43741			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1600.00
RENEW LHR DOOR								
REPAIR LHF DOOR , LHR FENDER & RR BUMPER								
E PNT98000								1400.00
RESPRAY LHF DOOR , LHR DOOR , LHR FENDER & RR BUMPER								
E PNT88000								120.00
REMOVE & REFIT LHR DOOR COMPONENT								
A 54900099								30.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								40.00
SUPPLY BODY PNL SEALANT								
M SUNDRY								20.00
Sundry								
M PANEL ASSY-REAR DOOR,LH					1.00	1290.00	20.00	1032.00
M HINGE ASSY-RR DOOR UPPER,LH					1.00	33.00	20.00	26.40
M HINGE ASSY-RR DOOR LOWER,LH					1.00	26.00	20.00	20.80
M GARNISH ASSY-RR DR FR FRAME,LH					1.00	49.00	20.00	39.20
M MOULDING ASSY-RR DR FRAME,LH					1.00	38.00	20.00	30.40
M GARNISH ASSY-RR DR RR FRAME,LH					1.00	48.00	20.00	38.40
M W/STRIP ASSY-RR DR BELT O/S LH					1.00	88.00	20.00	70.40
M GARNISH ASSY-RR DR SIDE LH					1.00	210.00	20.00	168.00
M GARNISH ASSY-RR DR SIDE,RH					1.00	210.00	20.00	168.00
M MOULDING ASSY-SIDE SILL,LH					1.00	129.00	20.00	103.20
SURVEYOR NAME : _____								
SURVEYOR SIGNATURE : _____								
DATE : _____								

Confirm & accepted by

REMARKS : _____

7% GST on **5026.80** **351.88**

Nett 5,026.80

Total Payable 5,378.68

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.