Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 5 January 2022 9:37 AM

To: Admin-D (LKKAuto); 'Teo, Grace'; 'Hwang, Shiang Yi'; assignments; SUR

Subject: RE: LKK/MC \ CMTD2103639/SYH(nr) - GBH356H | REQUEST FOR PRE-REPAIR

INSPECTION FOR SLK 2380P DOA: 08.12.2021

Attachments: LKKPhotosIn6_compressed.pdf; SLK 2380P LTA.pdf; SLK 2380P MARK EST.pdf; SLK

2380P PRELI REVISED.pdf

Dear Shiang Yi,

Enclosed preliminary revised of vehicle SLK 2380P

Date of survey: 9/12/2021

Number of days (estimated): 12 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Friday, 10 December 2021 10:42 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; 'Teo, Grace' <grace.teo@sompo.com.sg>; 'Hwang, Shiang Yi' <shiangyi.hwang@sompo.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: LKK/MC \ CMTD2103639/SYH(nr) - GBH356H | REQUEST FOR PRE-REPAIR INSPECTION FOR SLK 2380P DOA:

08.12.2021

Dear Shiang Yi,

Please be informed that we have inspected the vehicle SLK 2380P on 9/12/2021.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 9 December 2021 11:59 AM

To: 'Teo, Grace' <grace.teo@sompo.com.sg>; 'Hwang, Shiang Yi' <shiangyi.hwang@sompo.com.sg>; assignments

<assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: LKK/MC \ CMTD2103639/SYH(nr) - GBH356H | REQUEST FOR PRE-REPAIR INSPECTION FOR SLK 2380P DOA:

08.12.2021

Dear Sir / Mdm,

Thank you for your assignment.

Best Regards, Summer Lee | Admin LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: Teo, Grace <grace.teo@sompo.com.sg> Sent: Thursday, 9 December, 2021 11:50 AM

To: Ong Shiying <<u>shiying.ong@fastechauto.com.sg</u>>; Hwang, Shiang Yi <<u>shiangyi.hwang@sompo.com.sg</u>>; 'admin-

d@lkkauto.com' ; delkkauto.com">; delkkauto.com ; SUR ; SUR ; delkkauto.com; SUR <a href="mailto:sur@lkkau

Cc: Jason < Jason@fastechauto.com.sg>; Ashley Chia <ashley.chia@fastechauto.com.sg>

Subject: LKK/MC \ CMTD2103639/SYH(nr) - GBH356H | REQUEST FOR PRE-REPAIR INSPECTION FOR SLK 2380P DOA: 08.12.2021

Without Prejudice

Our Reference: CMTD2103639/SYH

Your Reference: SLK2380P

Hi Shi Ying,

We refer to your email reply of today and agreed to appoint **Mr. Marcus Chua** of **LKK Auto** to conduct the survey.

Hi LKK Auto,

Please arrange Mr. Marcus to survey for SLK2380P on a without prejudice and any admission of liability basis.

Please revert your report upon completion of survey to my colleague, Ms. Shiang Yi.

Please be informed that we have yet to receive our insured's accident report.

Thank you.

Please be informed that our office will relocate to #03-03 at Singapore Land Tower with effect from 1 Dec 2020. Kindly direct invoices and business correspondence to our new registered address.

Thank you.

[Working From Home with effect from 06 April 2020]

Best Regards **Grace Teo**Claims Division

D: 6329 5170 | T: 6461 6555

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #03-03 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Ong Shiying <<u>shiying.ong@fastechauto.com.sg</u>>

Sent: Thursday, December 9, 2021 11:41 AM

To: Teo, Grace <grace.teo@sompo.com.sg>; Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>

Cc: Jason Jason@fastechauto.com.sg; Ashley Chia Ashley.chia@fastechauto.com.sg;

Subject: RE: PRI \ CMTD2103639/SYH(nr) - GBH356H | REQUEST FOR PRE-REPAIR INSPECTION FOR SLK 2380P DOA: 08.12.2021

EXTERNAL SENDER: Do not click links or open attachments unless you recognize the sender and know the content is safe.

Without Prejudice

Dear Grace,

Please arrange (LKK Auto Consultants Pte Ltd - Marcus Chua) to conduct the pre- repair survey.

Thank You.

Best Regards, Shiying Fastech Auto Pte Ltd 1 Kaki Bukit Avenue 6 #01-46/48/50 Autobay Singapore 417883

Tel: 6746 5405 Fax: 6745 8520 Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/ claimant.

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 9 December 2021 11:36 am

To: Ong Shiying <shiying.ong@fastechauto.com.sg; Hwang, Shiang Yi <shiying.ong@fastechauto.com.sg; Hwang, Shiang Yi <shiying.ong@fastechauto.com.sg;

Cc: Jason <<u>Jason@fastechauto.com.sg</u>>; Ashley Chia <<u>ashley.chia@fastechauto.com.sg</u>>

Subject: PRI \ CMTD2103639/SYH(nr) - GBH356H | REQUEST FOR PRE-REPAIR INSPECTION FOR SLK 2380P DOA: 08.12.2021

Our Reference: CMTD2103639/SYH

Your Reference: SLK2380P

Attention:

M/S FASTECH AUTO PTE LTD

Dear Shi Ying,

ACCIDENT INVOLVING GBH356H & SLK2380P ON 08.12.2021

We refer to your Notice of Accident dated 09/12/2021.

Please be informed that **Ms. Hwang Shiang Yi** is the handler of this case who can be contacted at 63295 205/ shiangyi.hwang@sompo.com.sg

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

		Selection (Indicate as
Motor Surveyor	Surveyor	tick)
FormTeam Consultancy	Frankie Pang	
LKK Auto Consultants	Adrian Ling	
	Kenneth Kong	
	Marcus Chua	
Priority Services	Jimmy Lee	
Raleigh Services	Andrew Ow Yong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Please be informed that our office will relocate to #03-03 at Singapore Land Tower with effect from 1 Dec 2020. Kindly direct invoices and business correspondence to our new registered address.

Thank you.

[Working From Home with effect from 06 April 2020]

Best Regards
Grace Teo

Claims Division

D: 6329 5170 | **T**: 6461 6555

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #03-03 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Ong Shiying <shiying.ong@fastechauto.com.sg>

Sent: Thursday, December 9, 2021 9:53 AM

To: Claims - Motor Survey < MotorSurvey@sompo.com.sg>

Cc: Jason < <u>Jason@fastechauto.com.sg</u>>; Ashley Chia < <u>ashley.chia@fastechauto.com.sg</u>> Subject: REQUEST FOR PRE-REPAIR INSPECTION FOR SLK 2380P DOA: 08.12.2021

EXTERNAL SENDER: Do not click links or open attachments unless you recognize the sender and know the content is safe.

Without Prejudice

Dear Sir / Madam,

Your insured's vehicle: GBH 356H.

Date of accident: <u>08/12/2021</u>

Please arrange <u>Pre-repair Inspection</u> for my client's vehicle no: <u>SLK 2380P.</u>

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS

AMENDMENT NO. 1 OF 2016 paragraph 2.3, please provide a list of at least $\underline{10 \text{ motor surveyors}}$ within $\underline{2}$ days of the notice.

Thank you

Best Regards, Shiying Fastech Auto Pte Ltd 1 Kaki Bukit Avenue 6 #01-46/48/50 Autobay Singapore 417883

Tel: 6746 5405 Fax: 6745 8520

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/ claimant.