



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21012481/Bvf3n2	
			Date: 16/03/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 1432R	Veh. Inspected	SMG 4598A
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/12/21/7002	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	09/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA NOAH HYBRID 1.8X	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	ZWR800338478	Colour	WHITE
	Odometer	203719 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/65 R15	GENERAL ALTIMAX	6 mm
	L/H Front Tyre	205/65 R15	GENERAL ALTIMAX	6 mm
	R/H Rear Tyre	205/65 R15	GENERAL ALTIMAX	6 mm
	L/H Rear Tyre	205/65 R15	GENERAL ALTIMAX	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	03/12/2021	Inspection Date	10/12/2021
	Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	