

1 of 2 ?

100%

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSG INSURANCE (S) PTE LTD		Ref: CS/MSG21012482/Uvf3	
4 SHENTON WAY #21-01		Date: 09/12/2021	
SGX CENTRE 2 SINGAPORE 068807		Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBH 1983R	Veh. Inspected	YP 8681B
Policy No.	1001352443	Coverage (\$)	0.00
Claim No.	266618	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIN B MADI)	Assign Date	09/12/2021
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/12/2021	Inspection Date	09/12/2021
Survey held at	Blk 15 Kaki Bukit Road 4, Bartley Biz#01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			