

PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717
 Tel No. : 67433246 / 67438552 Fax No. : 67430013
 E-Mail : peoplevehicle@gmail.com
 Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

SOMPO INSURANCE (S) PTE LTD
 50 RAFFLES PLACE #05-01/06
 S'PORE LAND TOWER 048623

Attention : Motor Claim Department
 Contact : 6461 6555 Fax No. : 6221 3147

*Not Accid
 due
 to people recovery
 3 days
 15/12/21*

Estimate : ES21020

Date : 15/12/2021
 Vehicle Num. : SMN 7258 A
 Make/Model : MERCEDES BENZ CLA
 Chassis/Eng# :
 Accident Date : 08/12/2021
 Claim No. : TT 409-21
 Reference : GBG 8124 M
 Policy No. : NTUC 5112399402-02

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		NETT ITEMS :		
1.	1	HEAD LAMP R/H <i>510</i>		2,860.00
2.	1	BUMPER FRT <i>2000</i>		1,320.00
3.	1	BUMPER SENSOR R/H FRT <i>11</i>		190.00
4.	1	BUMPER SIDE RETAINER R/H FRT		56.00
Nett Total S\$:				4,426.00
10.00% Discount S\$:				442.60
				<hr/>
				3,983.40
LABOUR :				
REMOVE & REPLACE ACCIDENT DAMAGED PARTS				400.00 <i>200</i>
SPRAY PAINTING ACCIDENT AFFECTED PARTS				600.00 <i>400</i>
CHECK ALL LIGHTING AFTER REPAIR AND PROGRAMMING				300.00 <i>80</i>
Labour Total S\$:				<hr/>
				1,300.00

SingDollars : Five Thousand Two Hundred Eighty-Three & Cents Forty Only

E. & O.E.

Total S\$:

5,283.40

for PEOPLE'S VEHICLE RECOVERY SERVICE

Computer Generated Invoice.No Signature Required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: