

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21012516/Gvy3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 17/12/2021 SINGAPORE 068811 ATTN: YONG JOHNNY Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHA 1342G Veh. Inspected SLG 6770S Policy No. Coverage (\$) 0.00 Claim No. S1M03NZ8 Excess (\$) 0.00 **Assign Date** YONG JOHNNY 10/12/2021 Assign From **Vehicle Particulars & Condition** 2. **TOYOTA CAMRY 2.0** Make & Model 1998 c.c HIDDEN 2008 Engine No. Year of Reg. MR053BK4107034438 Chassis No. Colour **BLACK** Odometer 252024 KM Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 215/55 R17 HANKOOK 6 mm L/H Front Tyre 215/55 R17 HANKOOK 6 mm 215/55 R17 HANKOOK R/H Rear Tyre 6 mm L/H Rear Tyre 215/55 R17 HANKOOK 6 mm **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. 5. **General Information** 09/12/2021 10/12/2021 (03:00 PM) Inspect Date / Time Accident Date **ENG SOON PAINTING SVC** Survey held at BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Report Ref No. CS3/ASM21012516/Gvy3e2

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

10 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.