



10/2/2022

PAGE 1/2

© SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

ATTN: MARCUS.

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

WD: 12 days

Customer: CU0014956 / LONPAC
Chassis No: JHMRC1880HC203488
License No: SLR8925S
Mileage: 56161
Engine No: K24W72041132

Document No: SVO21062393
Printed By: JESHURUEBEN
Order Date: 13. December 2021
Order Time: 12:05:12 PM
Service Advisor: RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO: 76769)						
	OWNER: TAN TAI MENG						
	OWNER INSURER: LIBERTY INSURANCE						
	ACC DATE: 10/12/2021						
	SURVEYED BY: MARCUS (LKK)						
	DATE: 13/12/2021						
	REF NO: CC4/LPC21012537/Upa3						
	TP INSURER: LONPAC INSURANCE						
	TP VEH: GBC2818E						
73211-T6A-Q02	GLASS SET,RR.WINDSHIELD	1	1,078.20	25	808.65	56.61	865.26
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	19.20	25	28.80	2.02	30.82
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	18.00	25	13.50	0.95	14.45
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	18.00	25	13.50	0.95	14.45
73221-SR4-000	SPACERRR.W/SHIELD	4	4.20	25	12.60	0.88	13.48
73225-TM8-000	RUBBER AWINDSHIELD DAM	1	3.90	25	2.92	0.20	3.12
73226-SZW-000	DAMPERSTD 5X5	2	9.10	25	13.65	0.96	14.61
76711-T6A-003	CAPPVOT	1	5.20	25	3.90	0.27	4.17
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,141.90	25	856.42	59.95	916.37
34155-T6A-003	LIGHT ASSYL.LID	1	411.80	25	308.85	21.62	330.47
34150-T6A-003	LIGHT ASSY,R.LID	1	411.80	25	308.85	21.62	330.47
33500-T6A-003	TAILLIGHT ASSYR.	1	893.80	25	670.35	46.92	717.27
74440-T6A-003	WEATHERSTRIPTAILGATE	1	125.20	25	93.90	6.57	100.47
74800-TF0-J02	LOCKTAILGATE	1	197.70	25	148.27	10.38	158.65
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1	245.70	25	184.27	12.90	197.17
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	187.20	25	140.40	9.83	150.23
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER	1	220.00	25	165.00	11.55	176.55
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL	1	11.50	25	8.62	0.60	9.22
75701-T6A-000	EMBLEMH	1	28.10	25	21.07	1.47	22.54
04715-T6A-000ZZ	FACERR.BUMPER	1	573.20	25	429.90	30.09	459.99
91505-TM8-003	CLIP,BUMPER	9	2.30	25	15.52	1.09	16.61
33505-SLJ-013	REFLECTOR ASSYR.RR.	1	48.40	25	36.30	2.54	38.84
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	20.40	25	15.30	1.07	16.37
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	20.40	25	15.30	1.07	16.37
71502-T6A-003ZH	FACE,R.RR.BUMPER	1	81.90	25	61.42	4.30	65.72
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	110.50	25	82.87	5.80	88.67
84615-T6A-N23ZD	LINING COMP,R.RR.SIDGATE	1	752.30	25	564.22	39.50	603.72
38387-SLE-003	ANTENNA ASSY,L.RR.	1	64.60	25	48.45	3.39	51.84
66100-T6A-Q01ZZ	PANEL COMP,REAR	1	491.40	25	368.55	25.80	394.35
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	360.30	25	270.22	18.92	289.14
72841-SH3-315	OILSHEET	1	43.40	25	32.55	2.28	34.83
63320-T6A-300ZZ	GUTTER COMPR.RR.PILLAR	1	140.40	25	105.30	7.37	112.67
90650-TX6-A01	CLIPRR.COMBINATION LIGHT	1	2.10	25	1.57	0.11	1.68
	SUM PARTS:				6,230.99	436.18	6,667.17
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						

(S)
(S)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

**SERVICE PRE-INVOICE**GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0014956 / LONPAC
Chassis No: JHMRC1880HC203488
License No: SLR8925S
Mileage: 56161
Engine No: K24W72041132

Document No: SVO21062393
Printed By: JESHURUEBEN
Order Date: 13. December 2021
Order Time: 12:05:12 PM
Service Advisor: RUEBEN THOMAS

BML02I	EXT-YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	150.00	150.00	10.50	160.50
BA02R	EXT-YJ REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	160.00	160.00	11.20	171.20
BOJSE	0760 BODY JOINT SEALANT.	1	200.00	200.00	14.00	214.00
BOBC	0959 BODY UNDERSIDE COATING (N)	1	100.00	100.00	7.00	107.00
BP00R	EXT-YBH APPLY BODY UNDERSIDE COATING (N).	1	250.00	250.00	17.50	267.50
BG01S	EXT-YJ TO VACUUM & CLEAR SHATTERED GLASS	1	200.00	200.00	14.00	214.00
BC011R	0760 REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	350.00	350.00	24.50	374.50
BC012R	0760 RESET VEHICLE SMART ENTRY SYSTEM	1	350.00	350.00	24.50	374.50
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	350.00	350.00	24.50	374.50
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	650.00	650.00	45.50	695.50
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	550.00	550.00	38.50	588.50
BMF00D	EXT-YJ REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	450.00	450.00	31.50	481.50
BKRP02B	EXT-YJ CUT & RENEW RR FLOOR PANEL.STRAIGHTEN FENDERS ALIG RR CHASSIS INCLUDING FIITTING ON ATTACHMENT ITEMS.	1	6,175.00	6,175.00	432.25	6,607.25
BP06R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3,100.00	3,100.00	217.00	3,317.00
			SUM LABOUR:	13,055.00	913.85	13,968.85
BO-VK-ASTRO-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN	1	300.00	300.00	21.00	321.00
			SUM EXT SERVICE:	300.00	21.00	321.00
			TOTAL SGD	19,585.99	1,371.03	20,957.02
			Total Payable (SGD)			20,957.02

GST Amount is calculated from individual line(s)