ESTIMATED ACCIDENT REPAIR COST



REPORTED	14:06HRS	BUS REGISTRATION NUMBER	SBS3388M
ACCIDENT DATE	08-Dec-21	BUS TYPE (SD/DD)	DD
BUS CAPTAIN NAME	Muhamad Irfan Bin Abdul Malik	BUS ROUTE NUMBER	
THIRD PARTY CLAIM AGAINST	SMRT BUS - STRIDES	BUS ADVERTS	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	OS MIRROR ASSY CA	1506.22 51	\$ 966.22
2	REFLECTOR STICKER AR	1	\$ 40.00
		7% GST	\$ 70.44
		PARTS TOTAL COST	\$ 1,076.66

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

TO DISMANTLE & REPLACE :- OS MIRROR ASSY REFLECTOR STICKER		TOTAL COST	
		\$ 680.00	
SPRAY PAINTING \$640 PER PANEL LABOUR CHARGES \$650 PER DAY	7% GST	\$ 45.50	
COST CIDATES 9000 PER DAT	LABOUR TOTAL COST	\$ 695.50	

SECTION 3: NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

1331.72

BUS TYPE (SD / DD) DD LOSS OF USE COST

DATE IN

DATE & TIME SURVEY

DATE OUT

TOTAL NUMBER OF
DAYS

\$ 800.00

LKK Auto	Consultants	hence	notify
Control of the Contro	A STATE OF THE PARTY OF THE PAR		

the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

(RASIL
	Hp 90010088
	1 day
	13/12/21
	# 1350
in	after repri

SUMMARY			
SECTION NO.		COST	
1	\$	1,076.66	
2	\$	695.50	
3	\$	800.00	
TOTAL	\$	2,572.16	

PAGE 1