



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 10.12.2021
Emailed : 27.12.2021, 5.30pm
Date survey : 13.12.2021

VEHICLE NO : SMR 7700 R
MODEL : KIA SORENTO 2.4 A
WIP : 43862

Material	:	\$	5,433.60
Labour	:	\$	2,480.00
Sub-Total	:	\$	7,913.60
	:		-
Less Excess	:	\$	600.00
Total	:	\$	7,313.60
GST 7%	:	\$	511.95
Grand Total	:	\$	7,825.55
Finalise By/Date	:	LOI / 27/12/2021	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim

☐ Claim GIA / LTA fee

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 13/12/2021	Cust No/Name	LCV11499/LEK CHIN KWONG (LU ZENG GUANG)
	Reg No/Reg Date	SMR7700T*ECB1/ 14/11/2019
	Date In/Mileage	13/12/2021/ 19135
	Chassis/Package	KNAPH813ML5612855 /KC17
	Engine No	G4KJH768945
	Make/Model	KIA/SORENTO 2.4 A SX GDI SR
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	27/12/2021/ 16:48	BLE	260 / AiTing	43862

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, BONNET, REPAIR RH FRONT FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 600.00
E PNT98000 RESPRAY ON FRONT BUMPER, BONNET, RH FRONT FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 1050.00
E PNT88000 REMOVE & REINSTALL A/COND CONDENSOR & RADIATOR TO FACILITATE REPAIR				? 100.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 120.00
E PNT88000 REMOVE & REINSTALL FRON PARKING ASSIST SENSOR TO FACILITATE REPAIR				✓ 80.00
M SUNDRY SUNDRIES				✓ 20.00
S SPECIALISTJOB VACUUM & TOP UP A/COND GAS				? 80.00
E PNT88000 REPLACE FRONT SUPPORT PANEL → Supp.				400.00
X EXC EXCESS				-600.00
X PANEL ASSY-HOOD	1.00	✓ 1654.00	20.00	1323.20
X LAMP ASSY-HEAD,RH	1.00	✓ 2743.00	20.00	2194.40
X COVER-FR BUMPER UPR	1.00	✓ 561.00	20.00	448.80
X MOULDING-FRONT BUMPER LWR,RH	1.00	✓ 89.00	20.00	71.20
X SKID PLATE-FR BUMPER	1.00	✓ 111.00	20.00	88.80
X GRILLE-FRONT BUMPER FOG LAMP,R	1.00	✓ 81.00	20.00	64.80
X LAMP ASSY-FRONT FOG,RH	1.00	✓ 593.00	20.00	474.40
X CARRIER ASSY-FRONT END MODULE	1.00	? 760.00	20.00	608.00
X RESERVOIR & PUMP ASSY-WASHER	1.00	170.00	20.00	136.00
X TANK ASSY-RESERVOIR } Supp.	1.00	30.00	20.00	24.00

PRO-FORMA INVOICE

Co Req No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 13/12/2021	Cust No/Name
	Reg No/Reg Date
	Date In/Mileage
	Chassis/Package
	Engine No
	Make/Model
	Colour/Trim

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	27/12/2021/ 16:48	BLE	260 / AiTing	43862

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z TEXT AIG OD CLAIM DOA : 10.12.21 SURVEYOR STEVE LKK 13.12.21 POLICY NO : 1900246247-01 REPAIR 05 DAYS + 02 DAYS = 07 DAYS				
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	5,433.60		Nett	7,313.60
Labour	2,380.00	7% GST on	7313.60	511.95
Standard Menu	0.00			
Specialist Job	80.00		Total Payable	7,825.55
Diagnostics Job	0.00			
Sundry/Others	-580.00			
Total(w/o GST)	7,313.60			

**This is not an official tax invoice.
This is a computer generated document, no signature is required.**



Exceptional Journeys

INSURANCE CO.: AIG

Supplementary Parts For Registration No.: SMR 7700 R

	<u>Materials</u>	<u>Cost (\$)</u>
1	Reservoir & pump assy-washer ✓ CRV	170.00
2	Tank assy-reservoir ✓ CRV	30.00

Total Materials 200.00

Less 20% discount 40.00

Total after discount 160.00

	<u>Labour</u>	<u>Cost (\$)</u>
1	Replace front support panel	400.00 ✓

Total labour 400.00

Total amount 560.00

7% GST 39.20

Grand total \$ 599.20

Thank You.
Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SMR7700T

WIP: 43862 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	WASHER TANK	? / SUPP			
2	FRONT SUPPORT	? / SUPP	Jtk	- BR	
3	Radiator Spare tank	? / SUPP		- CRG	Steve 16/12/21
4	FRONT support part	? / SUPP		- BR	
5		? / SUPP			
6		? / SUPP		/	
7	Add labour 1 days -- \$400	? / SUPP		/	
8		? / SUPP			
9	Add repair days 2 days = total 7 days	? / SUPP		/	
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY

MODEL: SORENTO

SURVEYOR: STEVE




Fault Code Searching

Rescan

Erase All DTC

Clear DTC

Save



19/19

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
EPB	No Current DTC	Good
ABSESP	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No History or Pending DTC

S/W Ver.

M-E-K-01-00-0261

VCI Ver.

02.63

ECU Ver.

M-E-K-01-00-0200

OS Ver.

Android 10