



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21012568/Utf3e2	
			Date: 17/03/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SGM 2237U	Veh. Inspected	SMP 6973P
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2103671/GPL	Excess (\$)	0.00
	Assign From	MELVIN YE YONG KANG	Assign Date	13/12/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA NOAH HYBRID (A)	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	ZWR800387668	Colour	BLACK
	Odometer	121948 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	TOURADOR	6 mm
	L/H Front Tyre	195/65 R15	TOURADOR	6 mm
	R/H Rear Tyre	195/65 R15	TOURADOR	6 mm
	L/H Rear Tyre	195/65 R15	TOURADOR	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT N/S PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	11/12/2021	Inspection Date	14/12/2021
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	