

Section A - Accident Details

Registration Number	SHC4745Y
Case Reference Number	TAX/12/21/2015
Registration Date	8/1/2016
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	OH TECK PIEW
Type of Accident	Head to Rear
Accident Date and Time	6/12/2021 11:15 AM
Accident Reported Date and Time	7/12/2021 11:05 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24113283
Special Instruction to ARC, if any	TP / REAR RIGHT PORTION / AIG - LKK
Prepared Date and Time	9/12/2021 7:21 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$1,644.34	\$383.76
Total Other Cost	\$656.88	\$326.88
TOTAL COST	\$3,197.22	\$1,110.64
Lump Sum Total	\$3,200.00	\$1,200.00 (L/S)
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	GUO QIANG (LKK) / AIG
ARC / Surveyor Sign Off Date	13/12/2021 1:48 PM	10/12/2021 12:17 PM
Signature		
Remarks		LUMP SUM REPAIR / AFTER PAINT PHOTO .

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/12/2021

User ID : PohSuan

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	479.70	
	-20%	
	383.76	L/S \$1,100/-
	200.00	
	526.88	
	<u>1,110.64</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: