

CC3/AIG21012615/T1TCN2

ASS. REC. BY:

Tang JH

REF:

ALG

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. 2070173124

Claims No. 2726428568SG

Sum Insured: \_\_\_\_\_ Excess: hba -

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 9176K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REY / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: 5MX2084P Yr Regn: 2020, Dec.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 C.C. 1984Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 6890 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAAU 222F44M A028635

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/80R17R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kankook

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. \_\_\_\_\_ D.O.I. 13/12/21Survey held at Premium Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SUBMIT PRELI REPORT, WITHDRAW CLAIM

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: \_\_\_\_\_

Lump Sum / L.S. (F) \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0991/2021/JT  
DATE : 7-Dec-21  
WIP : 57488

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/12/21

## AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN SOON CHWEE  
ADDRESS : BLK 103 RIVERVALE WALK  
#09-72  
SINGAPORE 540103  
TELEPHONE : HP +65 93660078  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 2070173124  
VEHICLE NO : **SMX 2084 P**  
MODEL CODE : AUDI A4 2.0 TFSI S  
MODEL YEAR : 30/12/2020  
ENGINE NO : DEM 029387  
CHASSIS NO : WAUZZZF44MA028635  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 1-Dec-21  
PLACE OF ACCIDENT : LORONG 3 GEYLANG CAR PARK

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 2084 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N	\$ 360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR LHS REAR FENDER AND LHS TAILLAMP PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 2,100.00	500
3	TO RESPRAY REAR BUMPER, LHS REAR FENDER AND LHS TAILLAMP PANEL.		\$ 3,000.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	✓
TOTAL LABOUR CHARGES		:	\$ 5,652.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 2084 P**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,342.00	de ✓
2	REAR BUMPER FIXING PARTS	1	\$ 166.00	X
3	REAR BUMPER SECURING STRIP- UPPER	1	\$ 112.00	X
4	REAR BUMPER SECURING STRIP- LOWER	1	\$ 223.00	X
5	REAR BUMPER SPOILER	1	\$ 249.00	X
6	REAR BUMPER BRACKET - LH	1	\$ 204.00	?
7	REAR LIGHT REFLECTOR OUTER - LH	1	\$ 43.00	?
8	REAR LIGHT REFLECTOR INNER - LH	1	TBC	
9	LED TAIL LIGHT - LH	1	\$ 1,019.00	X
10	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 46.00	?
11	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 166.00	?
12	REAR BUMPER GUIDE SECTION UPPER - LH	1	\$ 44.00	?
13	EXHAUST TRIM - LH	1	\$ 354.00	X
14	AERIAL RETAINER - LH	1	\$ 26.00	X
15	AERIAL TELEPHONE	1	\$ 174.00	X
16	REAR VENT TRIM	1	\$ 68.00	X
17	SUNDRIES		\$ 250.00	?
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 5,486.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 5,652.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 11,138.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

Tanpin 9749526  
Not Insurance Claim  
13/12/21 C 1015  
3 days Exp to be advise  
Tanpin @ 11/12/21

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT



# CERTIFICATE OF INSURANCE

## AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TAN SOON CHWEE  
Period of Insurance : 30 Dec 2020 To 29 Dec 2021  
Engine No. : DEM 029387  
Chassis No. : WAUZZZF44MA028635

Vehicle No. : SMX2084P  
Policy No. : 2070173124  
Endorsement No. :  
Issued Date : 12 Jan 2021

### ABOUT THE COVER

Make/Model : AUDI A4 2.0 TFSI S TRONIC  
Engine Capacity/Tonnage : 1,984.00 CC  
Driver Restriction : NA  
Person or Classes of Persons Entitled to Drive\* :  
Sum Insured : Market Value  
Off Peak Car : No  
First Year of Registration : 2020  
Insuring with COE/PARF : Yes

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition  
Mileage Condition : Unlimited Mileage  
Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

### EXCESS

Section 1  
Fire - \$0 Own Damage - \$1100 Theft - \$0 Flood Cover - \$1100

Section 2  
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)  
TAN SOON CHWEE - \$1100 (Own Damage), \$1100 (Flood Cover)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125276

PREMIUM LEASING -SCS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE  
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**

This computer generated document does not require a signature.

Steffany Loh