

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 10/12/2021
TP Veh Reg No: SKB101B

Estimate No: EST2100329

Date: 13 Dec 2021

Veh Reg No: **SKR6218A**

Make/Model: TOYOTA VIOS J GRADE
MT

Chasis No: MHFBT9F3806027521

Reg. Date: 26/02/2015

Your Ref No: SKB101B

Estimate Repair Cost to Vehicle No :SKR6218A

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC REAR BUMPER	482.80	
2	1 PC REAR BUMPER SIDE RETAINER RH	113.90	
3	1 PC REAR BUMPER SMALL RETAINER RH	72.70	
4	1 PC TAIL LAMP RH	375.80	
5	1 PC REAR BUMPER REINFORCEMENT	316.60	
		1,361.80	
	Less 25%	340.45	1,021.36
	Special Net		
6	2 PCS "L" PLATE BRACKETS	100.00	
7	1 SET REAR BUMPER CLIPS	60.00	
8	1 PC REAR BUMPER STICKER	280.00	
		440.00	440.00
	Labour		
9	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	800.00	
10	1 TO SPRAY PAINTING	700.00	
11	1 TO REMOVE AND REFIT INNER TRIM	100.00	
12	1 TO CHECK WIRING	50.00	
13	1 TO REPLACE STICKERS	80.00	
		1,730.00	1,730.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

97495749
Tanghin 97495749 / 62563561
up' 13/12/21 @ 2pm
1/3 survey after repair
Tanghin @ lkkauto.com
03days - 4days

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 **FAX:** 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 10/12/2021
TP Veh Reg No: SKB101B

Estimate No: EST2100329
Date: 13 Dec 2021
Veh Reg No: SKR6218A
Make/Model: TOYOTA VIOS J GRADE
MT
Chasis No: MHFBT9F3806027521
Reg. Date: 26/02/2015
Your Ref No: SKB101B

Estimate Repair Cost to Vehicle No :SKR6218A

Quantity	Description	List Price	Amount
		S\$	S\$
		Total	S\$ 3,191.36
		Add GST @ 7%	223.40
		Total Amount Payable	<u>S\$ 3,414.76</u>

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FOUR HUNDRED FOURTEEN AND CENTS SEVENTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE