



# SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368

Email: [service@smemotor.com.sg](mailto:service@smemotor.com.sg) Website: [www.smemotor.com.sg](http://www.smemotor.com.sg)

Co. & GST Reg. No: 201119451E

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

TEL: 63896111 FAX: 62247478

ATTN: Motor Claim Department

Your Ref No : 21/CN/TP-232(12)

Claim Type : Third Party

Accident Date : 11/12/2021

TP Veh Reg No : GBF8700E

Claim No :

No : EST21121301

Date : 13/12/2021

Policy No : Z/21/VC00/110035

Veh Reg No : GBC1043E

Make / Model : NISSAN CABSTAR

Chassis No : 0

Engine No :

Reg. No :

## ESTIMATE FOR VEHICLE NO: GBC1043E

Discription	Quantity	Unit Price	Amount
<b>NET PRICE:</b>			\$S \$S
1 REAR TAIL BOARD <i>sent</i>	1 PC		\$1,459.60
2 REAR TAIL LAMP <i>sent</i>	2 PCS	\$266.30	\$532.60
3 REAR RH TAIL LAMP PANEL <i>sent</i>	1 PC		\$70.00
4 REAR FLOOR BOARD <i>R</i>	1 PC		\$4,819.40 <i>X</i>
5 REAR TAIL BOARD HINGE RH <i>sent</i>	1 PC		\$288.90
6 REAR TAIL BOARD LOCK RH <i>sent</i>	1 PC		\$40.20 <i>X</i>
7 REAR RH CORNER RUBBER BUSH <i>NA</i>	1 PC		\$19.00 <i>X</i>
	TOTAL		<b>\$7,229.70</b>
	-10.00%		<b>\$722.97</b>
			<b>\$6,506.73</b>

### SPECIAL NET

1 REAR TAIL BOARD "70KM/H" STICKER <i>sent</i>			\$25.00 <i>10</i>
2 REAR TAIL BOARD "12 PAX" STICKER <i>sent</i>			\$25.00 <i>10</i>
3 REAR NUMBER PLATE <i>sent</i>			\$20.00 <i>15</i>
4 REVERSE SENSOR <i>sent</i>			\$300.00 <i>200</i>
	TOTAL		<b>\$370.00</b>

### Labour

1 WIRE CHECKING			\$30.00 <i>20</i>
2 LABOUR CHARGE			\$1,000.00 <i>800</i>
3 SPRAY PAINTING			\$900.00 <i>580</i>
	TOTAL		<b>\$1,930.00</b>

For SME MOTOR PTE LTD

AUTHORISED SIGNATURE

*not approved*  
*16/12/21*  
*take photo of the car*  
*4 days*  
*1/5 @ 3000*

Amount Before Excess **\$8,806.73**  
Add GST @7% **\$616.47**  
Total Amount Payable **\$9,423.20**

LKK Auto Services hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: