



CYCLE & CARRIAGE

AG- OD (REVERT)
SURVEY: 14/12/21
LICK - STEVE

VEHICLE NO : SMM6952R

MODEL : MIT/ATRAGE 1.2 CVT

WIP : 18662

Material	:	\$	<u>5,635.42</u>
Labour	:	\$	<u>8,690.00</u>
Sub-Total	:	\$	<u>14,325.42</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>14,325.42</u>
GST 7%	:	\$	<u>1,002.78</u>
Grand Total	:	\$	<u>15,328.20</u>
re - Finalise By/Date : <u>LARRY ON 04/01/22</u>			

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 16 WORKING DAYS + 6 days (3 weekends)
+ 2 days P.H.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 14/12/2021	Cust No/Name /TING MIN WEE, BERNARD (CHEN MIN
	Reg No/Reg Date SMM6952R / 10/07/2019
	Date In/Mileage 14/12/2021/ 22307
	Chassis/Package MMBSTA13AKH000729 /#
	Engine No 3A92UHM3658
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	04/01/2022/ 09:09	BLC	884 / Lauro Songcuan	18662			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2925.00 ✓
RENEW REAR AIRDAM, REAR BUMPER, BOOTLID, REAR END PANEL, REAR LAMP HOUSING RH & LH, REPAIR REAR FENDER RH								
E PNT88000								60.00 ✓
REMOVE & INSTALL PARKING SENSOR								
E PNT88000								300.00 ✓
REMOVE & INSTALL REAR COMPARTMENT TRIMS								
E PNT98000								2100.00 ✓
SPRAY PAINT FOR REAR AIRDAM, REAR BUMPER, REAR END PANEL, REAR LAMP HOUSING RH & LH, REAR FENDER RH& LH								
A 54900099								30.00 ✓
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00 ✓
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								40.00 ✓
SUPPLY C&C LOGO								
M SUNDRY								80.00 ✓
APPLY SEALANT FOR AFFECTED PORTIONS								
M SUNDRY								20.00 ✓
SUNDRIES								
A 13900099								225.00 ✓
REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR → <i>Supp.</i>								
S SPECIALISTJOB								50.00 ✓
SUPPLY REAR LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)								
S SPECIALISTJOB								220.00 ✓
SUPPLY ONE SET OF REVERSE SENSOR (ATTRAGE)								
E PNT88000								1350.00 ✓
REPLACE LH REAR FENDER, REPAIR FLOOR PANEL → <i>Supp.</i>								
E PNT88000								500.00 ✓
MOUNTED ONTO FLOOR BENCH TO FACILITATE REPAIR → <i>Supp.</i>								
E PNT88000								240.00 ✓
REMOVE & REFIT REAR WINDSCREEN GLASS → <i>Supp.</i>								
M SUNDRY								80.00 ✓

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 14/12/2021	Cust No/Name	/TING MIN WEE, BERNARD (CHEN MIN
	Reg No/Reg Date	SMM6952R / 10/07/2019
	Date In/Mileage	14/12/2021/ 22307
	Chassis/Package	MMBSTA13AKH000729 /#
	Engine No	3A92UHM3658
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	04/01/2022/ 09:09	BLC	884 / Lauro Songcuan	18662

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
SUPPLY REAR WINDSCREEN GLASS SEALANT → <i>Supp.</i>				350.00 ✓
E PNT98000				
SPRAY PAINT FLOOR PANEL → <i>Supp.</i>				
X UNPAINTED BODYKITS	1.00	✓1643.00	00.00	1643.00 ✓
X FACE,RR BUMPER	✓1.00	751.00	23.00	578.27 ✓
X BRACKET,RR BUMPER,LH	✓1.00	28.00	23.00	21.56 ✓
X BRACKET,RR BUMPER,RH	1.00	✓28.00	23.00	21.56 ✓
X WEATHERSTRIP,TRUNK LID	1.00	✓157.00	23.00	120.89 ✓
X PANEL,TRUNK LID	1.00	✓795.00	23.00	612.15 ✓
X HINGE,TRUNK LID,RH	1.00	✓203.00	23.00	156.31 ✓
X HINGE,TRUNK LID,LH	1.00	✓203.00	23.00	156.31 ✓
X LATCH,TRUNK LID	1.00	✓218.00	23.00	167.86 ✓
X PANEL,RR END	1.00	✓427.00	23.00	328.79 ✓
X PANEL,RR COMB LAMP HSG,LH	1.00	60.00	23.00	46.20 ✓
X MARK,THREE-DIA	1.00	70.00	23.00	53.90 ✓
X MARK,ATTRAGE	1.00	21.00	23.00	16.17 ✓
X BOARD,TRUNK ROOM FLOOR	1.00	195.00	23.00	150.15 ✓
X TRIM,RR END	1.00	66.00	23.00	50.82 ✓
X TRIM,TRUNK ROOM SIDE,RH	1.00	160.00	23.00	123.20 ✓
X TRIM,TRUNK ROOM SIDE,LH	1.00	160.00	23.00	123.20 ✓
X LAMP ASSY,COMB,RR LH	1.00	✓337.00	23.00	259.49 ✓
X LAMP ASSY,COMB,RR RH	1.00	✓337.00	23.00	259.49 ✓
X COVER,RR VENTILATOR	1.00	✓40.00	23.00	30.80 ✓
X CLIP,FR BUMPER → <i>Supp.</i>	10.00	4.00	23.00	30.80 ✓
X PANEL,QTR,OTR LH → <i>Supp.</i>	1.00	✓759.00	23.00	584.43 ✓
X BUZZER,KEYLESS OPERATIO,RR	1.00	✓91.00	23.00	70.07 ✓
X EMBLEM MIVEC TECHNOLOGY → <i>Supp.</i>	1.00	✓30.00	00.00	30.00 ✓
Z TEXT				
AIG OD CLAIM - TP RECOVERY				✓
DOA: 11/12/2021				
SURVEY: STEVE (LKK) 14/12/2021				
16 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	5,635.42		Nett	14,325.42
Labour	8,200.00			
Standard Menu	0.00	7% GST on	14325.42	1002.78
Specialist Job	270.00			
Diagnostics Job	0.00		Total Payable	15,328.20
Sundry/Others	220.00			
Total(w/o GST)	14,325.42			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : **AIG**

Supplementary For Registration No.: **SMM 6952 R**

<u>Materials</u>		<u>Cost (\$)</u>
1	Clip, FR Bumper (10 pcs)	NEC 40.00
2	Panel, Qtr, Otr LH	DD 759.00
		<u>799.00</u>
	23% Discount	<u>183.77</u>
		615.23
3	Emblem Mivec Technology	30.00 NEC
		<u>645.23</u>
<u>Labour</u>		
1	Remove & Install Fuel Tank to Facilitate Repair	225.00 ✓
2	Replace LH Rear Fender, Repair Floor Panel	✓ 1,350.00
3	Mounted onto Floor Bench to Facilitate Repair	500.00 ✓
4	Remove & Install Rear Windscreen Glass	✓ 240.00
5	Supply Rear Windscreen Sealant	80.00 ✓
6	Spray Paint Floor Panel	✓ 350.00
		<u>2,745.00</u>
	Labour & Materials	3,390.23
	7% Gst	237.32
	Total	<u>3,627.55</u>

Thank You.

Yours faithfully

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE

TEL: 6568 4658

FAX : 6567 5258