

# PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183  
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.  
Date  
Service Advisor  
Pages  
Regn No  
Model No

PA/OD/1008/2021/JT  
20-Dec-21  
CHANG  
1 of 1  
SML 277 B  
AUDI R5 4 AVANT 2.9 TFSI

Quantity	Description		Unit Price	Amount
<u>Parts</u>				
1	FLAT CONTACT HOUSING <i>com</i>	1	\$ 16.00	
2	PRESSURE PIPE <i>bt</i>	1	\$ 1,368.00	
GRAND TOTAL			\$ 1,384.00	

*PRM*  
*PRM*

For Premium Automobiles Pte Ltd



Authorised Signature

Car-in

17/12/21

wip= 58130

Wiam/Choy



Ata-Rasul

-10 days

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NDRA.KHAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

### DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>OK</i>	1	\$ 5,937.00	
2	FRONT BUMPER SECURING STRIP <sup>?</sup>	1	\$ 53.00	
3	FRONT BUMPER SECURING STRIP INNER <sup>?</sup>	1	\$ 36.00	
4	FRONT BUMPER AIR GUIDE - LH / RH <sup>?</sup>	2	\$ 334.00	
5	FRONT BUMPER SPOILER (BLACK) <sup>?</sup>	1	\$ 613.00	
6	FRONT BUMPER GRILLE - CENTER <sup>?</sup>	1	\$ 722.00	
7	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <sup>?</sup>	1	\$ 350.00	
8	FRONT BUMPER LOWER SPOILER TRIM <sup>?</sup>	1	\$ 708.00	
9	FRONT BUMPER SPOILER - LOWER <sup>?</sup>	1	\$ 856.00	
10	FRONT BUMPER SPOILER - LH <sup>?</sup>	1	\$ 676.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH <sup>?</sup>	1	\$ 736.00	
12	FRONT AIR GUIDE INNER - LH <sup>?</sup>	1	\$ 75.00	
13	FRONT AIR GUIDE - LH / RH <sup>?</sup>	2	\$ 452.00	
14	RADIATOR GRILLE <i>OK</i>	1	\$ 4,172.00	
15	"RS4" EMBLEM <i>OK</i>	1	\$ 128.00	
16	RADIATOR GRILLE CAP <sup>?</sup>	1	\$ 211.00	
17	FRONT PARKING AID SENSOR SUPPORT - LH / RH <sup>?</sup>	2	\$ 102.00	
18	RADIATOR GRILLE UPPER COVER <sup>? OK</sup>	1	\$ 155.00	
19	RADIATOR GRILLE LOWER COVER <sup>? OK</sup>	1	\$ 213.00	
20	FRONT BUMPER REINFORCEMENT BEAM <i>OK</i>	1	\$ 845.00	
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 17,374.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55, UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT BUMPER FOAM FILLER PIECE <i>cm</i>	1	\$	297.00
22	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$	134.00
23	FRONT BUMPER BRACKET - LH <i>? cm</i>	1	\$	228.00
24	FRONT BUMPER TOP COVER <i>de</i>	1	\$	242.00
25	"CAUTION" STICKER <i>ne</i>	1	\$	14.00
26	AIR COND STICKER <i>ne</i>	1	\$	8.00
27	FRONT LOCK CARRIER BRACKET <i>? cm</i>	1	\$	244.00
28	FRONT BUMPER SUPPORT - LH / RH <i>cm/ne</i>	2	\$	58.00
29	POP RIVET <i>ne</i>	4	\$	4.00
30	HORN - LH	1	\$	201.00
31	HORN SUPPORT - LH	1	\$	50.00
32	FRONT APARKING AID SENSOR - INNER / OUTER	2		TBC
33	FRONT PARKING AID SENSOR SEAL RING <i>ne</i>	4	\$	9.00
34	FRONT BUMPER WIRING SET	1	\$	510.00
35	LIGENCE PLATE SUPPORT <i>cut</i>	1	\$	621.00
36	FRONT FENDER - LH <i>st</i>	1	\$	5,665.00
37	POP RIVET <i>ne</i>	3	\$	10.00
38	FRONT FENDER CLOING ELEMENT - LH <i>ne</i>	1	\$	72.00
39	FRONT FENDER BRACKET - LH <i>st</i>	1	\$	35.00
40	FRONT FENDER RETAINER - LH	1	\$	49.00
<b>SUB TOTAL SPARE PARTS</b>		:	\$	<b>8,451.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NDRA.KHAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT FENDER TRIM - LH <i>de/</i>	1	\$	402.00
42	FRONT FENDER ADAPTER - LH <i>?</i>	1	\$	86.00
43	FRONT FENDER BRACE - LH <i>?</i>	1	\$	118.00
44	FRONT FENDER BRACKET CENTER - LH <i>?</i>	1	\$	49.00
45	FRONT FENDER BRACKET BACK - LH <i>?</i>	1	\$	32.00
46	FRONT FENDER CLOSING ELEMENT - LH <i>?</i>	1	\$	33.00
47	FRONT WHEEL HOUSING LINER - LH <i>?</i>	1	\$	296.00
48	FRONT BACK PANEL COVER - LH <i>?</i>	1	\$	26.00
49	FRONT WHEEL SPOILER <i>X</i>	1	\$	264.00
50	FRONT SPOILER - LH <i>X</i>	1	\$	35.00
51	STONE CHIP GUARD - LH <i>?</i>	1	\$	51.00
52	FRONT FENDER FLEDGE COVER LONG - LH <i>nee/</i>	1	\$	31.00
53	FRONT FENDER FLDGE COVER SHORT - LH <i>nee/</i>	1	\$	23.00
54	BONNET <i>bt/</i>	1	\$	3,246.00
55	BONNET HINGE - LH/RH <i>?</i>	2	\$	610.00
56	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>nee/</i>	3	\$	84.00
57	BONNET GAS FILLED <i>X</i>	2	\$	241.00
58	BONNET SOUND ABSOBER <i>X</i>	1	\$	343.00
59	BONNET SOUND ABSOBER OUTER <i>X</i>	1	\$	215.00
60	BONNET STRIKER - LH/RH <i>bt/</i>	1	\$	100.00
<b>SUB TOTAL SPARE PARTS</b>			<b>:</b>	<b>\$ 6,285.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	BONNET LOCK <i>bt/LH</i>	<del>1</del>	\$	427.00
62	CONNECTOR HOUSING ?	2	\$	26.00
63	CONNECTOR HOUSING BRACKET ?	2	\$	19.00
64	BONNET BOWDEN CABLE - CENTER ?	1	\$	58.00
65	BONNET BOWDEN CABLE COVER ?	1	\$	10.00
66	BONNET BOWDEN CABLE - OUTER <i>bt</i>	1	\$	58.00
67	BONNET RELEASE LEVER ?	1	\$	14.00
68	BONNET LOCK CABLE ?	1	\$	74.00
69	PLENUM CHAMBER X	1	\$	97.00
70	HEADLIGHT MATRIX BEAM - LH <i>ca</i>	1	\$	13,044.00
71	HEADLIGHT POWER MODULE ?	1	\$	1,206.00
72	HEADLIGHT CONTROL UNIT ?	1	\$	751.00
73	HEADLIGHT HOSE ?	1	\$	36.00
74	SPACER ?	3	\$	122.00
75	LIFT CYLINDER - LH ?	1	\$	210.00
76	LIFT CYLINDER BRACKET ?	1	\$	6.00
77	LIFT CYLINDER CORRUGATED PIPE ?	1	\$	93.00
78	FRONT LOCK CARRIER <i>ca</i>	1	\$	1,332.00
79	RADIATOR COOLANT SUPPORT <i>ca</i>	<del>1</del>	\$	76.00
80	AIRCOND CONDENSER <i>bt</i>	1	\$	622.00
<b>SUB TOTAL SPARE PARTS</b>		:	\$	<b>18,281.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 LIBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	HIGH PRESSURE VALVE ?	1	\$ 51.00	
82	A/C PRESSURE SENSOR ? cra	1	\$ 186.00	
83	REFRIGERANT LINE - SUCTION ?	1	\$ 167.00	
84	REFRIGERANT LINE - PRESSURE HOSE ?	1	\$ 340.00	
85	REFRIGERANT LINE - SUCTION FRONT ?	1	\$ 248.00	
86	OUTSIDE TEMPERATURE SENSOR BRACKET ? cra	1	\$ 19.00	
87	AIR COOLER CHARGED ? bt	1	\$ 1,340.00	
88	RADIATOR COOLANT COOLER ? bt	1	\$ 1,190.00	
89	RADIATOR ADDITIONAL COOLER - CENTER ?	1	\$ 2,724.00	
90	RADIATOR ADDITIONAL COOLER - SUPERCOOLING LEVEL ?	1	\$ 2,545.00	
91	RADIATOR AIR GUIDE ?	1	\$ 42.00	
92	RADIATOR RUBBER BUSH LOWER INSULATOR ?	2	\$ 18.00	
93	RADIATOR RUBBER BUSH MOUNTING LOWER ?	2	\$ 25.00	
94	RADIATOR FAN RING ? ca	1	\$ 306.00	
95	RADIATOR FAN CONTROL UNIT - LH / RH ?	2	\$ 3,018.00	
96	RADIATOR AIR GUIDE LH (INNER / OUTER) ? ca	2	\$ 93.00	
97	RADIATOR AIR GUIDE RH - INNER / OUTER ? ca	2	\$ 93.00	
98	RADIATOR AIR GUIDE - LOWER FRONT ?	1	\$ 46.00	
99	RADIATOR AIR GUIDE - UPPER / LOWER ?	2	\$ 38.00	
100	RADIATOR AIR GUIDE - RH ?	1	\$ 109.00	
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 12,598.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 277 B**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
101	RADIATOR COOLANT <i>OK ✓</i>	6	\$	266.00
102	RADIATOR INTAKE AIR DUCT - RH <i>?</i>	1	\$	22.00
103	RADIATOR INTAKE AIR GUIDE HOSE <i>?</i>	1	\$	53.00
104	RADIATOR INTAKE HOSE <i>?</i>	1	\$	113.00
105	FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH <i>OK ✓</i>	2	\$	1,282.00
106	FRONT WINDOW GUIDE TRIM STRIP - LH / RH <i>X</i>	2	\$	594.00
107	FRONT NO PLATE <i>54 ✓</i>	S/N	\$	60.00
108	SUNDRIES <i>?</i>		\$	500.00
<b>TOTAL SPARE PARTS</b>		:	\$	<b>65,879.00</b>
<b>TOTAL LABOUR CHARGES</b>		:	\$	<b>16,924.00</b>
<b>GRAND TOTAL</b>		:	\$	<b>82,803.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.