

REF: MSG/ 21012708/KV

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST: 201001158E RCB NO: 201001158E

Not Authenticated
Punery B4 pain 4 days

M/S: NTUC INCOME INSURANCE CO-OPERATIVE LTD
 73 BRAS BASAH ROAD
 #05-01 NTUC TRADE UNION HOUSE
 SINGAPORE 189556

TEL: 67886616 FAX: 67883777
 ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK
 Claim Type: Third Party
 Accident Date: 10/12/2021
 TP Veh Reg No: FBL1819L

Estimate No: ES2290073/AMK
 Date: 20 Jan 2022
 Policy No: GA588510
 Veh Reg No: SMQ7558T
 Make/Model: TOYOTA SIENTA 1.5X
 AUTO
 Chassis No: NHP1707172757
 Engine No: 1NZR783014
 Reg. Date: 29/11/2019

82961.08

Estimate Repair Cost to Vehicle No :SMQ7558T

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	<i>Brk Rd</i> 309.10	1 PC	309.10	<i>✓</i>
2 REAR BUMPER TOP PROTECTOR	<i>nd</i> 189.50	1 PC	189.50	<i>✓</i>
3 REAR BUMPER TRIANGLE GARNISH	<i>nd</i> 45.20	1 PC	45.20	<i>✓</i>
4 REAR BUMPER LH SIDE PAD	<i>nd</i> 129.10	1 PC	129.10	<i>✓</i>
5 REAR BUMPER CLIP	<i>nd</i> 3.50	6 PC	21.00	<i>✓</i>
6 REAR TAILGATE	<i>nd</i> 1,110.90	1 PC	1,110.90	<i>✓</i>
7 TAILGATE LOGO	<i>nd</i> 67.50	1 PC	67.50	<i>✓</i>
8 TAILGATE EMBLEM 'HYBRID'	<i>nd</i> 56.00	1 PC	56.00	<i>✓</i>
9 TAILGATE WINDSCREEN GLASS MOULDING	<i>nd</i> 99.80	1 PC	99.80	<i>✓</i>
			2,028.10	
		Less 25%	507.03	1,521.08
Special Net				
10 REVERSE SENSOR	200	1 SET	200.00	<i>✓</i>
11 REAR WINDSCREEN GLASS SEALANT	40	1 PC	40.00	<i>✓</i>
			240.00	240.00
Labour				
12 REMOVE AND REFIX REAR WINDSCREEN GLASS	120	1 LA	120.00	<i>✓</i>
13 REMOVE & REFIX REAR BUMPER & ATTACHMENTS, TAILGATE & ATTACHMENTS, KNOCKING & REPAIR REAR END PANEL & REALIGN THE SAME	500	1 LA	500.00	<i>400</i>
14 PUTTY & RESPRAY REAR BUMPER, TAILGATE, REAR END PANEL & ALL AFFECTED AREAS	700	1 LA	700.00	<i>600</i>
15 REMOVE & REFIX REVERSE CAMERA, RESET & REALIGN THE SAME	50	1 LA	50.00	<i>✓</i>
16 RUSTPROOFING	30	1 LA	30.00	<i>✓</i>
			1,400.00	1,400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: