

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : TP/122021/5129
Date : 14-12-2021
Accident Date : 13-12-2021

Vehicle Details

Make & Model : HONDA SHUTTLE HYBRID 1.5
AUTO
Chassis No : GP72203332
Registration No : SNC4703Y

Third Party Vehicle Details

Registration No : SKX4439K

S/N	Description	Qty	Amount (\$S)
1	REAR TAILGATE / <i>pac</i>	1.00	\$1,293.50
2	REAR TAILGATE GLASS MOULDING	1.00	\$153.20
3	REAR TAILGATE "SHUTTLE" EMBLEM	1.00	\$55.20
4	REAR TAILGATE "HYBRID" EMBLEM	1.00	\$80.10
5	REAR BUMPER CHROME MOULDING <i>X MN</i>	1.00	\$220.20
			\$1,802.20
			Discount: -20% (\$360.44)
			\$1,441.76
6	REAR WINDSCREEN GUM / <i>MLC</i>	1.00	\$60.00
7	TO REMOVE AND REFIX REAR WINDSCREEN	1.00	\$150.00 <i>120</i>
8	TO REPAIR DAMAGES	1.00	\$380.00 <i>200</i>
9	TO SPRAY PAINTING	1.00	\$380.00

Subtotal w/o GST: \$2,411.76

*4 Days.
P/P
before paint photos
GMO Q&P
29/12/21*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.