

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair (Supplementary)

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : TP/122021/5133
Date : 14-12-2021
Accident Date : 13-12-2021

Vehicle Details

Make & Model : Toyota VIOS 1.5 G (AUTO)
Chassis No : MR2B23F3101183644
Registration No : SMN8742L

Third Party Vehicle Details

Registration No : YN9698H

S/N	Description	Qty	Amount (\$\$)
1	FRONT GRILLE ✓ CUT	1.00	\$77.80
2	REAR RH TAILLAMP PANEL ✓ BT	1.00	\$128.20
3	REAR LH TAILLAMP PANEL ✓ BT	1.00	\$128.20
4	REAR LH TAILLAMP LOWER BRACKET ✓ BR	1.00	\$59.80

Discount: -25%

\$394.00
(\$98.50)

\$295.50

Subtotal w/o GST:

\$295.50