



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/ASM21012296/Vqy3-1

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Ref: ~~CS3/ASM21012296/Vqy3-1~~
Date: ~~06/12/2021~~ 15/12/2021
Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SH 8765G	Veh. Inspected	SFR 5087B
Policy No.		Coverage (\$)	0.00
Claim No.	S1M03NHZ	Excess (\$)	0.00
Assign From	OH VALE	Assign Date	06/12/2021 02/12/2021

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	02/12/2021	Inspection Date	06/12/2021
Survey held at	DREAMWORKS GARAGE 25 KAKI BUKIT ROAD 4, #06-55, SYNERGY @ KB, SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.