

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1014/2021/TF
DATE : 15-Dec-21
WIP : 44486

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/12/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Taufikh

5 days - ok - Johnny Boo

16-Feb-22

OWNER'S NAME : MR NG INN THENG
ADDRESS : 1 RIVER VALLEY CLOSE
SINGAPORE 238427
TELEPHONE : HP +65 97601001
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210032440
VEHICLE NO : **SKA 9800 M**
MODEL CODE : AUDI A4 2.0 TFSI S tronic
MODEL YEAR : 30/3/2021
ENGINE NO : DEM 028304
CHASSIS NO : WAUZZZF47MN005701
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Dec-21
PLACE OF ACCIDENT : INSIDE CARPARK OF CINELEISURE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKA 9800 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR , HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$	700.00	
3	TO RENEW LHS FRONT FENDER INNER AIRCON PIPES. TO CARRY OUT VACUUM AND REGAS.	S/N \$	280.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	\$ 1,500.00
5	TO RESPRAY FRONT BUMPER AND BOTH FRONT FENDER.	\$	3,000.00	\$ 1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 7,452.00	\$ 3,822.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKA 9800 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,233.00	\$	1,786.40
2	FRONT BUMPER FIXING PARTS	1	\$ 358.00		
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00	\$	56.32
4	FRONT BUMPER LOWER GRILLE - CENTER	1	\$ 196.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 262.00	\$	209.20
6	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 88.00	\$	40.08
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	1	\$ 262.00		
8	FRONT BUMPER AIR GRILLE - LH / RH	2	\$ 270.00	\$	108.00
9	FRONT BUMPER AIR GRILLE TRIM - LH / RH	2	\$ 96.00		
10	FRONT RADIATOR GRILLE	1	\$ 1,580.00		
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 189.00		
12	FRONT BUMPER CARRIER	1	\$ 845.00		
13	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 72.00	\$	57.44
14	FRONT BUMPER TOP COVER	1	\$ 127.00		
15	CAUTION STICKER	1	\$ 14.00		
16	A/C STICKER	1	\$ 8.00		
17	FRONT LOCK CARRIER BRACKET	1	\$ 137.00		
18	FRONT BUMPER SUPPORT - LH / RH	2	\$ 58.00		
19	RIVET	4	\$ 4.00	\$	2.56
20	FRONT BUMPER PARKING AID SENSOR - OUTER	2	TBC		
SUB TOTAL SPARE PARTS		:	\$ 6,870.00	\$	2,260.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKA 9800 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>2,260.00</i>
21	FRONT PARKING AID SEAL RING	4	\$ 9.00		
22	FRONT BUMPER WIRING SET	1	\$ 577.00		
23	FRONT FENDER - LH / RH	2	\$ 2,184.00	<i>\$</i>	<i>1,747.20</i>
24	FRONT FENDER ATTACHMENT PARTS	1	\$ 202.00		
25	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 144.00	<i>\$</i>	<i>115.04</i>
26	FRONT FENDER BRACKET - LH / RH	2	\$ 70.00		
27	RIVET	12	\$ 40.00	<i>\$</i>	<i>31.68</i>
28	FRONT FENDER BRACE - LH / RH	2	\$ 236.00	<i>\$</i>	<i>188.80</i>
29	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 477.00		
30	FRONT WHEEL SPOILER - LH / RH	2	\$ 146.00		
31	FRONT WHEEL SPOILER TRIM - LH / RH	2	\$ 71.00		
32	FRONT FENDER TOP COVER - LH / RH	2	\$ 62.00	<i>\$</i>	<i>49.28</i>
33	FRONT HEADLIGHT TOP COVER - LH / RH	2	\$ 88.00	<i>\$</i>	<i>68.96</i>
34	FRONT HEADLIGHT	2	\$ 15,370.00		
35	FRONT HEADLIGHT LIFT CYLINDER - LH / RH	2	\$ 420.00		
36	FRONT HEADLIGHT LIFT CYLINDER BRACKET	2	\$ 12.00		
37	A/C CORRUGATED PIPE	1	TBC		
38	A/C REFRIGERANT PIPE	4	\$ 1,278.00		
39	FRONT NO. PLATE	S/N	\$ 60.00		
40	SUNDRIES		\$ 300.00		
TOTAL SPARE PARTS			\$ 28,616.00	<i>\$</i>	<i>4,460.96</i>
TOTAL LABOUR CHARGES			\$ 7,452.00	<i>\$</i>	<i>3,822.00</i>
GRAND TOTAL			\$ 36,068.00	<i>\$</i>	<i>8,282.96</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-12/02/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT