

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS4/CTI21012739/PQY3E2

**Date:** 06/01/2022

### REFERENCE

Insured/Claimant:	MOHAMMAD SUHAIMI BIN JAMIL	Policy No:	DMPCSNW00199852101		
Date of Loss:	11/12/2021	Nature of Claim:	OD	Claim No:	SNM21D207212/C01/TAYHP

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW6077A		
Make & Model:	MITSUBISHI LANCER, 1.5 MIVEC A/T ELEGANCE 2WD 4DR (A)	Engine No:	4A910126216
Reg. Date:	05/04/2010 (Man. Year: 2009)	Chassis No:	JMYSRCY2AAU000424
Colour:	Black	Odometer:	0 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$26,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Arivo 5 mm	Rear Left Side:	Arivo 5 mm
Front Right Side:	Arivo 5 mm	Rear Right Side:	Arivo 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	50.00	0.00	50.00	100.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>50.00</b>	<b>0.00</b>	<b>50.00</b>	<b>100.00</b>
<b>- Excess (S\$)</b>	0.00	500.00	-500.00	
<b>(S\$)</b>	50.00	-500.00	550.00	1,100.00
<b>+ GST 7.00/0.00% (S\$)</b>	3.50	0.00	3.50	100.00
<b>Nett Amount (S\$)</b>	<b>53.50</b>	<b>-500.00</b>	<b>553.50</b>	<b>1,034.58</b>

### INSPECTION

Date of Assignment:	16/12/2021 Present Location:	Cheng Hoe Motor Pte Ltd
Date Inspected:	17/12/2021 Inspected At:	10 Ang Mo Kio Ind Park 2A, #01-04 Ang Mo Kio Autopoint, Singapore 568047
Estimated Period of Repair:	0.0 days	

**Adjuster:** Sherwin Beh Swee Yang

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$26,000.00
OMV :	\$18,060.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$15,988.00
COE Rebate (2) :	\$ 9,687.00
Total Rebate (1) + (2) = :	\$ 9,687.00

The total amount incurred will be Market Value \$26,000.00 minus Total Rebate \$9,687.00 = \$16,313.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

Reference		
Part Source: MRM-SG    Version: 1.0 (Last Synchronised: 05 Jan 2022)		
Parts:	143	MITSUBISHI LANCER 1.5 MIVEC A/T ELEGANCE 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SJW6077A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	1) Towing	New	50.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>50.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >