

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 12/12/2021

TP Veh Reg No: SDW3232J

Estimate No: ES2191288/AMK

Date: 03 Jan 2022

Policy No: MP316643

Veh Reg No: SKV4470D

Make/Model: MAZDA CX-5

Chassis No: JM6KE1032G0327361

Engine No: PY30438863

Reg. Date: 18/09/2015

*Not Authorized
 11/1/2022
 Penny After Rain*

4 days

Estimate Repair Cost to Vehicle No :SKV4470D

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 FRONT BUMPER	1,023.10	1 PC	<i>Bz</i> 1,023.10	✓
2 FRONT BUMPER SPONGE	108.50	1 PC	108.50	✓
3 FRONT BUMPER REINFORCEMENT	543.00	1 PC	543.00	✓
4 FRONT BUMPER LH SIDE COVER	<i>CU</i> 45.20	1 PC	<i>Bz</i> 45.20	✓
5 FRONT BUMPER LH SIDE RETAINER	18.55	1 PC	<i>Bz</i> 18.55	✓
6 FRONT BUMPER CLIP	5.50	6 PC	<i>Bz</i> 33.00	✓
7 FRONT GRILLE HOUSING	945.20	1 PC	<i>CM</i> 945.20	✓
8 FRONT GRILLE LOGO	101.20	1 PC	<i>Bz</i> 101.20	✓
9 FRONT GRILLE OUTER CHROME	340.00	1 PC	<i>CM</i> 340.00	✓
10 FRONT BUMPER LH PARKING SENSOR	203.60	1 PC	<i>CM</i> 203.60	✓
11 BONNET	1,227.70	1 PC	<i>Bz</i> 1,227.70	✓
12 FRONT LH FENDER WHEEL ARC GARNISH	186.70	1 PC	<i>Bz</i> 186.70	✓
13 HEADLAMP LH	2,920.60	1 PC	<i>CU</i> 2,920.60	✓
14 FRONT GRILLE RIVET	8.50	7 PC	<i>Bz</i> 59.50	✓
			7,755.85	
		Less 20%	1,551.17	6,204.68
Special Net				
15 FRONT NUMBER PLATE	35.00	1 PC	<i>Bz</i> 35.00	✓
			35.00	35.00
Labour				
16 REMOVE & REFIT FRT BUMPER & ATTACHMENTS, GRILLE, HEADLAMP, BONNET & ATTACHMENTS & REALIGN THE SAME	500.00	1 LA	500.00	<i>400</i>
17 PUTTY & RESPRAY FRT BUMPER, BONNET, FRT LH FENDER & ALL AFFECTED AREAS	700.00	1 LA	700.00	<i>480</i>
18 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,230.00	1,230.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: