

CARIS AUTOWORKS PTE LTD
 160 SIN MING DRIVE
 #05-03 SIN MING AUTOCITY
 SINGAPORE 575722
 (COMPANY REGISTRATION NO: 200923135D)
 TEL: 62589831
 FAX: 62585349

ESTIMATE REPAIR COST FOR NISSAN (X-TRAIL 2.0) REG NO : SKA 488 R

S\$

1 PC	BUMPER (REAR)	793.10
1 PC	BUMPER REINFORCMENT (REAR)	696.20
4 PCS	BUMPER RETAINER (REAR)(PER PC \$55.10)	220.40
1 PC	BUMPER STAY (REAR RIGHT)	250.60
1 PC	BUMPER DOOR LOCK STRIKER (REAR)	78.10
1 SET	PARKING SENSOR (REAR)	278.40

TOTAL	2316.80
LESS 10%	231.68
TOTAL	2085.12

LABOUR & MISC CHARGES

PANEL KNOCKING	1000.00
SPRAY PAINTING	800.00
BODY CLIPS & SCREWS	100.00
WIRE CHECKING & DIAGNOSTIC	80.00

TOTAL	4065.12
-------	---------