

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	HSBC LIFE (SING)	APORE) PTE LTD	Ref	CC4/ASM20005206/Epa3q2-1	
	10 MARINA BOUL #48-01 MARINA B 2SINGAPORE 018	AY FINANCIAL CENTRE TOWER	Date	e: 17/07/2023	
	ATTN:VALE OH		Cod	le: HSB	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 5242U	Veh. Inspected	GBA 1881M	
	Policy No.	P2348706	Coverage (\$)	0.00	
	Claim No.	S0M02LYA	Excess (\$)	0.00	
	Assign From		Assign Date	14/04/2020	
2. Vehicle Particulars & Condition					
	Make & Model	FIAT DOBLO	c.c	1910	
	Engine No.	HIDDEN	Year of Reg.	2007	
	Chassis No.	ZFA22300005500012	Colour	SILVER	
	Odometer	271403 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	185/65 R15	YOKOHAMA	5 mm	
	L/H Front Tyre	185/65 R15	YOKOHAMA	5 mm	
	R/H Rear Tyre	185/65 R15	YOKOHAMA	5 mm	
	L/H Rear Tyre	185/65 R15	YOKOHAMA	5 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	09/04/2020	Inspection Date	14/04/2020	
	Survey held at	held at MY CAR CONSULTANT PTE LTD			
		60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				