

Our Job Ref No : 305497953
Date : 16/12/21

ENGINEERING
ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM


To : LKK
Attn : Mr Thevan
Vehicle Reg No. : SHA2175R CTPL


Fax :
13/12/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SLE4168E
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost** \$0.00
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost \$3,050.00
3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : Ms. Loke YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : Thevan
Date : 17/12/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA2175A

Make : HYUNDAI

Model : I-40

Date: 14/12/2021

Insurance: NTUC

MVA:MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$1,052.20
10	FRT BUMPER CLIPS			\$22.00
1	FRT BUMPER SIDE BRACKET RH			\$28.60
1	FRT FENDER RH			\$663.00
1	FRT FENDER SHIELD RH			\$174.90
1	HEADLAMP RH			\$1,800.00
1	HEADLAMP SUPPORT PANEL			\$907.40
1	FRT WHEEL HUB CAP RH			\$217.20
	SUB TOTAL			\$4,865.30
	LESS 20%			\$973.06
	DISCOUNTED TOTAL			\$3,892.24
				\$-
	Labour Charge			
	PANEL BEATING			\$900.00
	SPRAY PAINTING CHARGE			\$800.00
	TUFF KOTE			\$60.00
	CHECK ALL LIGHTING			\$60.00
	TOTAL LABOUR			\$1,820.00
	ESTIMATE TOTAL			\$5,712.24

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuvan@Lkhauto.com

82235769

L/S after repair photo

14/12/21 16/5

3 clays w p

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: