

Our Job Ref No 305498029
Date : 20/12/2021

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : THEVAN
: SHA9173A

Fax :

DOA 15/12/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- GBE7362J
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$4,210.68
 - (b) Labour Charges \$1,360.00
 - Total for Part-By-Part Repair Cost** \$5,570.68
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____
3. Estimated normal period for repairs: 3 working days
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : _____
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : THEVAN
Date : 21/12/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

TYPE OF CASE : CHINA

SURVEY BY : LKK – THEVAN

DATE : _____

STATEMENT OF PARTS AND LABOUR COSTS			
DESCRIPTION	QTY	ESTIMATE	REMARKS
REAR BUMPER STAY LH		\$138.10	LIST / DT 110.48
REAR BUMPER STAY RH		\$138.10	LIST / DT 110.48
REAR BUMPER UNDER COVER LH		\$108.00	LIST / Cut 86.40
REAR BUMPER LOWER MOULDING		\$155.00	LIST / Cut 124.00
REAR BUMPER CENTRE UNDER COVER		\$225.00	LIST / Cut 180.00
CHECK ITEM			
REAR BUMPER BEAM	1	\$394.80	LIST / DT
DOOR LAMP	1	\$201.50	LIST / Cut 161.20
TOTAL:		\$1,360.50	JUMANI

China (P/P)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 16.12.2021

Jumar

Time: 11:00:10

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305498029
REGN NO : SHA9173A ✓
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 15.12.2021 18:45
ACCIDENT DATE : 15.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	/cut
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	/scr
0003	04-01-0104-2288-G	BEAM-RR BUMPER	1	493.50	394.80	394.80	? /DT
0004	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	/nec
0005	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	22.00	20.00	17.60	/nec
0006	28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1 N	50.00	2.00-	50.00	/cr9
0007	04-01-0104-2370-G	LAMP ASSY-REAR FOG ✓	1	201.50	20.00	161.20	xscu cra
0008	09-01-0104-2133-G	ANTENNA ASSY-SMARTKEY	10	405.00	20.00	324.00	? xscu
0009	04-01-0104-2256-G	PANEL ASSY-TAIL GATE#	1	2,480.40	20.00	1,984.32	/DT
0010	05-01-0199-0032-A	WINDSCREEN AHESIVE-310MLC	2 N	46.00	2.00-	46.00	/nec
0011	04-01-0104-2271-G	EMBLEM-IONIQ	1	31.30	20.00	25.04	/nec
0012	04-01-0104-2270-G	EMBLEM-HYBRID	1	24.30	20.00	19.44	/nec
0013	28-01-0103-0007-A	FRONT DOOR LOGO CCTPL MOQ30	1 N	30.00	2.00-	30.00	/nec ✓

COMFORTDELGRO ENGINEERING PTE LTD

Date: 16.12.2021

Time: 11:00:10

Page: 2

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305498029
REGN NO : SHA9173A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 15.12.2021 18:4
ACCIDENT DATE : 15.12.2021

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT					
0014 28-01-0103-0008-A	REAR DOOR TEL NUMBER CCTP	1	N	30.00	0.20	30.00	✓ n/c
0015 28-01-9999-2026-A	APP LOGO REAR BONNET CCPL	1	N	40.00	0.02	40.00	✓ n/c
0016 04-01-0104-2175-G	SYMBOL MARK-H	1		28.00	20.00	22.40	✓ n/c ✓
SUB-TOTAL						3,844.36	

JOB NATURE

0000 PB	PANEL BEATING	800.00	700
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 17-01	CHECK ALL LIGHTING	50.00	20
0003 L	REMOVE/REFIX REVERSE SENSOR	50.00	20 ✓
0004 L	REMOVE/REFIX REAR W/SCREEN GLASS	120.00	✓ ✓
SUB-TOTAL		1,620.00	