

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	15 Dec 2021 13:35	Clm Veh Model Changed		[] Merimen Administrator
2	15 Dec 2021 13:35	Clm Created	Reg No: SLK6084T. Policy No: 2100498703-04. Acct Date: 2021/12/14. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R21CF0001	[I] Merimen Administrator
3	20 Dec 2021 10:40	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
4	20 Dec 2021 10:40	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
5	20 Dec 2021 10:40	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	20 Dec 2021 10:40	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/12/29	[A] CELINE FONG
7	20 Dec 2021 10:40	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
8	20 Dec 2021 10:40	Clm Registration Modified	Rep:1137->200611.	[A] CELINE FONG
9	20 Dec 2021 10:40	Clm Veh Model Changed	(204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] CELINE FONG
10	20 Dec 2021 10:46	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CELINE FONG
11	20 Dec 2021 15:31	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	20 Dec 2021 15:31	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	20 Dec 2021 15:31	Clm Dtl Modified	JPJ Reg. Date: -> 2017/01/20.	[A] Elaine Kuan Hwa Meen
14	20 Dec 2021 15:31	Clm Details Notified		[A] Elaine Kuan Hwa Meen
15	20 Dec 2021 16:25	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/12/29	[A] DENISE TAY KWEE CHENG
16	20 Dec 2021 17:28	Clm Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Hor, Yinrul
17	21 Dec 2021 07:12	Adj Mandate Request	Cur.Reg:9702.00:Damage consistent Repair cost economical	[A] DENISE TAY KWEE CHENG
18	21 Dec 2021 09:58	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/12/29. Mandate Remarks: Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after re	[I] Lim, Kok-Chong
19	21 Dec 2021 09:58	Adj Mandate Set	Approved:9702.00:Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2750452	20 Dec 2021 15:31:44	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLK6084T		11.00

